

36. 23- 22E

Grover "enderson, well no. 2.

Mapleton, Ks.

|             |     |                |
|-------------|-----|----------------|
| Soil        | 2   |                |
| clay        | 10  |                |
| lim e       | 16  |                |
| sh. dark    | 20  |                |
| lime        | 23  |                |
| shale blue  | 45  |                |
| lime        | 48  |                |
| shale light | 73  |                |
| lime shells | 88  |                |
| shale       | 90  |                |
| lime shells | 98  |                |
| shale       | 103 |                |
| lime hard   | 118 | bad crevice    |
| shale       | 121 |                |
| lime shells | 130 |                |
| shale. lt.  | 155 |                |
| lime hard   | 158 |                |
| sh. lt.     | 190 | B              |
| lime hard   | 200 |                |
| sh. blue    | 203 | P              |
| lime, hard  | 222 | little water   |
| sh. blue    | 232 |                |
| lime shells | 236 |                |
| sh. blue    | 240 |                |
| lime shells | 242 | L              |
| sh. blue    | 250 | FS             |
| lime hard   | 280 |                |
| sh. blue    | 285 |                |
| lime shells | 290 |                |
| sh. white   | 303 |                |
| sand water  | 305 | sq show of oil |
| sh. white   | 340 |                |
| lime hard   | 342 |                |
| shale blue  | 380 |                |
| lime hard   | 382 |                |
| sh. blue    | 400 |                |
| lime hard   | 402 |                |
| sh. lt.     | 450 |                |
| sh. dk.     | 460 |                |
| sh. sandy   | 488 | UBV            |
| sh. lt.     | 555 |                |
| sand broken | 565 | LBV gas        |
| sh. dk.     | 580 | sandy          |
| sh. dark    | 622 |                |
| sand broken | 627 |                |
| sand white  | 635 | Tucker         |
| chat        | 640 | Miss 2.        |
| sand broken | 650 | T.D. Dry hole. |

23-23E