

G

5

Company: J. W. Jones, et al

Sec. 36 T. 23 R. 24

Farm: Emerson

No. 1

Loc. Nw SE SE

Contractor: Claude Crowder ^{gas}

County: Bourbon

Total Depth: 340

Prod.- gas

Formation

Thickness Depth

Formation	Thickness	Depth
soil	2	2
clay	6	8
lime	8	16
shale, black	3	19
shale, blue	13	32
lime	1	33
shale	9	42
lime, broken	5	47
shale	8	55
lime	17	72
shale	1	73
lime	1	74
shale	6	80
lime	4	84
shale	41	125
lime	2	127
shale, dark	25	152
shale	6	158
lime, broken	5	163
shale, light	11	174
lime	2	176
shale	2	178
lime	1	179
shale	2	181
shale, light	44	225
shale, dark	5	230
lime, broken	6	236
shale, dark	10	246
shale, light	41	287
shale, black; show gas	5	292
shale, sandy	29	321
gas sand	2	323
shale, sandy	10	333
shale, white	1	334
sandstone, broken	4	338
sandstone, gas	2	340