

1-23-25E⁰_V

Company Tri State Gas Co.


Sec. 7 T. 23 R. 25
Loc. NW¹/₄

Farm Hamm No. 1

Total Depth 420
Comm. Feb. 6, 1930 Comp.

County Linn

Shot or Treated
Contractor
Issued



Casing
20 in. 10 in.
15 1-2 8 1-4
12 1-2 6 5-8
13 3-8 5 3-16

Elevation
Production

Figures Indicate Bottom of Formation

soil	3	
clay	11	
lime	18	
dk shale	44	
lime	46	
dk shale	55	
w shale	63	
lime	83	BFS
dk shale	88	
lime	90	
dk shale	179	
lime	182	
dk shale	197	
lime	204	
blk sha e	253	
oil sand	260	little gas X 0.5%
1 sandy shale	275	
dk shale	280	
1 shale	313	
sand	325	
dk shale	337	
sand	373	little gas X
blk shale	389	
1 shale	393	
blk shale	409	little gas X
sand	418	
dk shale	420	T.D.

7-23-25 E

Tri State Gas Company
Dry Hole plugged and abandoned
All casing pulled.
Feb. 5, 1930

Sec. 7, Twp. 23, Range 25
Linn County, Kansas.
Hamm #1

3 Soil	3	
8 Clay	11	
7 Lime	18	
26 Dark shale	44	
22 Lime	46	
9 Dark shale	55	
8 W. Shale	63	
20 Lime	83	
5 Dark shale	88	
2 Lime	90	
89 Dark shale	179	
3 Lime	182	
15 Dark shale	197	
7 Lime	204	
10 Black shale	214	
39 Dark shale	253	
7 Oil sand	260	Little gas
15 Light sandy shale	275	S.L.M.-265
5 Dark shale	280	
33 Light shale	313	
12 Sand	325	
12 Dark shale	337	
36 Sand	373	Little gas
16 Black shale	389	
4 Light shale	393	
16 Black shale	409	Little gas
9 Sand	418	
2 Dark shale	420	S.L.M. 419 T.D.

