

State Geological Survey
WICHITA, BRANCH

15-011-20166

30-25-22E

Company: 4 O Company
Sec. 30, Twp. 25, Rge. 22
Contractor: Dorwin Jackson

Farm: Lord Well # 1
Location: NWSEW County: Bourbon

Date: Aug 9th to 15th 1974

0	1	Top Soil			
25	26	Lime			
2	28	Black Shale			
8	36	Lime			
15	51	Sand			
2	53	Lime			
10	63	Sand			
2	65	Shale	1	667	Coal
15	80	Sand	11	678	Shale
7	87	Shale	4	682	Black shale
21	108	Lime	4	686	Lime
17	125	Shale	19	705	Shale
13	138	Lime	18	723	Sandy Shale
2	140	Lime shells	4	727	Sand
5	145	Black Shale	15	742	Shale T. D.
7	152	Lime Shale Shells			
16	168	Lime			
5	173	Lime shells			
10	183	Lime			
25	208	Lime shells			
17	225	Sandy shale			
17	242	Shale			
23	265	Lime			
9	274	Shale			
12	286	Lime			
5	291	Lime shells			
5	296	Lime			
6	302	Sand			
25	327	Shale			
14	341	Sandy Shale			
24	365	Shale			
5	370	Lime			
5	375	Sandy Shale			
39	414	Lime			
2	416	Black Shale			
27	443	Lime Shells			
12	455	Sandy shale			
74	529	Shale			
2	531	Lime			
29	560	Shale			
2	562	Lime			
5	567	Shale			
2	569	Coal			
10	579	Shale			
7	586	Sandy shale			
2	588	Black Shale			
8	596	Sandy shale			
19	615	Shale			
2	617	Sandy shale			
35	652	Black Shale			
14	666	Sand			

