

Company-
Farm- Boyer

DAVIS & IVES

No. 1

SEC. 25 T. 26 R. 12E
SE SE NW

25-26-12E

County Greenwood
KANSAS

Total Depth. 1675

Comm. 11-8-50

Comp. 1-8-51

Shot or Treated.

Contractor. Davis & Ives

Issued. 1-31-53

CASING:

Elevation. _____

Production. Dry

Figures Indicate Bottom of Formations.

surface	14
shale	60
lime	105
shale	115
red rock	130
shale	135
lime	138
red rock	148
shale	161
lime	170
shale	175
red rock	186
shale	210
sand wtr	263
shale	335
lime	347
shale	488
lime	491
shale	505
lime	546
sand	550
lime	554
shale	590
lime	650
shale	746
lime	816
shale	910
lime	960
shale	962
lime	966
shale	980
lime	1048
sand broken lime	1090
sand, shale	1167
lime	1190
shale	1246
lime	1263
shale	1265
lime	1274
shale	1294
lime	1298
shale	1303
sand	1307
shale	1336
sand	1344
shale	1393
coal	1395
shale	1611

slate	1628
shale	1658
chat	1675
Total Depth	
Tops:	
Miss.	1633-73

