
WELL LOG BUREAU—KANSAS GEOLOGICAL SOCIETY
509 East Murdock, Wichita, Kansas

Company- MORRISON DRILLING CO. INC. ET AL
Farm- Matson No. 1

SEC. 7 T. 26 R. 2E
NE SE NE

Total Depth. 3013½
Comm. 8-7-51 Comp. 8-17-51
Shot or Treated.
Contractor. Morrison Drlg. Co. Inc.
Issued. 1-26-52

County Sedgwick
KANSAS



CASING:
5" 3002

Elevation. 1434

Production. dry

Figures Indicate Bottom of Formations.

cement	50- 96
shale & lime brks	175
broken lime	300
lime	530
shale & shells	560
redrock & shale	590
lime & shale	740
lime	800
shale & shells	1300
lime	1330
shale & shells	1400
lime & shale	1600
shale & shells	1710
broken lime	1745
shale	1800
lime	2030
lime & shale	2165
lime	2500
broken lime	2594
lime	2600
lime & shale	2709
lime broken	2771
shale & lime brks	2868
lime & shale	3005, RTD
sand	3013½
Total depth	

Scout Top:
Vergis 3000