

WELL LOG BUREAU — KANSAS GEOLOGICAL SOCIETY  
412 UNION NATIONAL BANK BUILDING - WICHITA, KANSAS

COMPANY

Stearns & Streeter

SEC. 31 T. 26 R. 8 E  
LOC. SWe Lot 7.

FARM Snyder

NO. 1.

TOTAL DEPTH 2745'

COUNTY Butler

COMM. 10-11-21

COMP. 12-1-21

SHOT OR TREATED 20 Qts. 2620-26

CONTRACTOR

ISSUED



CASING

20		10	1444'
15½	136'	8¼	1622'
12½	1010'	6%	2423'
13%		5¼	

ELEVATION 1577

PRODUCTION

40 Bbls.

FIGURES INDICATE BOTTOM OF FORMATIONS

soil	5
lime	35
red rock	45
lime	55
shale	100
red rock	210
lime	215
shale	250
sand, 2 BW	260
shale	510
lime	525
shale	483
sand, 18 BW 483	493
shale	710
lime	725
shale	753
lime	770
shale	800
lime	825
shale	830
lime	840
shale	940
sand, 2 BW	975
lime	985
shale	995
lime	1000
shale	1010
lime, 2 BW	1020
shale	1070
lime	1140
shale	1155
lime	1175
shale	1210
lime	1245
sand	1250
lime	1275
shale	1215
lime	1225
shale	1235
lime	1245
shale	1400
lime	1444
shale	1475
lime	1480
shale, BW	1550
wtr sand	1580
lime	1615
shale	1770
lime	1785
shale	18 300
lime	1925

shale	2077
lime	2150
shale	2185
lime	2240
shale	2250
lime	2260
shale	2300
lime	2310
shale	2313
lime	2323
shale, cave	2385
lime	2395
shale	2445
lime	2455
shale	2618
lime	2619
shale	2625
SLM at 2629	
rock pink	2710
oil sand	2720
shale blk	2745
Total Depth.	

oil gravity 40-41

This well put on pump Dec. 22, 1921 and after the head was pumped off it pumped about 40 BPD and gradually settled down to 40/4 Bbls.

The well was shut down 1-5-22 to 1-10, while installing gas engine and when started up pumped 175 Bbls in 7 hrs and pumped off.

January 11, 1922, it pumped 100 Bbls and Jan 12, it pumped 40 Bbls. The well has never made wtr or SS and throughout down it makes up the production.

HAL REDMON  
311 INSURANCE BLDG.  
WICHITA 2, KANSAS

HAL REDMON, INC.