


8-28-11E

County Greenwood
 KANSAS

Total Depth. 1260
 Comm. 11-26-41
 Shot or Treated.
 Contractor.
 Issued. 1-31-53

Comp. 3-20-42



CASING:

Elevation. _____

Production. Dry

Figure in North Column of Formations.

soil	9	lime	1223 $\frac{1}{2}$
shale	33	lime	1226 $\frac{1}{2}$
lime	42	some oil	
shale	52	lime	1260
lime	55	Total Depth	
shale	62		
lime	75		
shale	85		
red rock	105		
lime	120		
shale	138		
lime	149		
shale	166		
lime	175		
shale	177		
lime	185		
shale	195		
sandy lime	210		
shale	225		
lime	226		
shale	236		
shale	270		
sand HFV	290		
shale	342		
lime	350		
shale	356		
shale	367		
lime	370		
shale	375		
red rock	388		
lime	390		
red rock	415		
lime	431		
shale	475		
sand	518		
shale	610		
lime	625		
shale	650		
lime	660	shale	1095
shale	736	lime	1185
lime oil show	745	shale	1187
lime	750	lime	1191
lime	836	lime oily	1193
shale	890	shale	1195
shale	1047	lime	1200
lime	1059	lime 2 BW	1202
shale	1068	lime	1211
lime	1078	shale blk	1216
sandy lime	1085		