

1-30-24E

Company

300' North of Main North Entry

Farm Mine No. 14

No. 2 A

Sec. 1 T. 30 R. 24

Loc. Between NW $\frac{1}{4}$ & SW $\frac{1}{4}$ NE $\frac{1}{4}$ NE $\frac{1}{4}$

County Crawford

Total Depth 98'

Comm.

Comp.


Shot or Treated

Contractor

Issued

Casing

20 in.	10 in.
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16



Elevation

Production

Figures Indicate Bottom of Formation

<u>FT</u>	<u>IN</u>		<u>FT</u>	<u>IN</u>
14		surface	14	
17	10	shale and sandstone	31	10
2	9	blue and black shale	34	7
	7	coal	35	2
24		shale and sandstone	59	2
5	5	blue and black shale	64	7
	5	coal	65	
17	6	drab gritty shale	82	6
5	8	sandstone	88	2
4	2	drab shale	92	4
2	10	coal	95	2
	8	blue clay	95	10
1	2	soft black rash	97	
	5	blue clay	97	5
	7	drab clay	98	