

1-30-24

Company

600' East of the 6th NE Entry.

Sec. 1 T. 30 R. 24

Loc. NE¹/₄ SE¹/₄ NE¹/₄

County Crawford

Farm

No. 9 A

Total Depth 100' 5"


Comm.

Comp.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

<u>FT</u>	<u>IN</u>		<u>FT</u>	<u>IN</u>
15		surface	15	
20	8	shale and sandstone	35	8
3	6	blue and black shale	39	2
	10	coal	40	
21	10	shale and sandstone	61	10
8	10	blue and black shale	70	8
	4	coal	71	
6	3	drab shale	77	3
18	9	sandstone, softer at bottom	96	
3	1	coal	99	1
1	4	blue clay	100	5

Driller--L. L. Brown