

1-30-24E

Company

335' Northeast of Hole No. 6

Farm Mine No. 14

No. 10 A

Sec. 1 T. 30 R. 24

Loc. NE $\frac{1}{4}$ NW $\frac{1}{4}$ NE $\frac{1}{4}$

County Crawford

Total Depth 111' 4"

Comm.

Comp.

Shot or Treated

Contractor

Issued

| | | | |
|--|--|--|--|
| | | | |
| | | | |
| | | | |
| | | | |

Casing

| | |
|--------|--------|
| 20 in. | 10 in. |
| 15 1/2 | 8 1/4 |
| 12 1/2 | 6 5/8 |
| 13 3/8 | 5 3/16 |

Elevation

Production

Figures Indicate Bottom of Formation

| <u>FT</u> | <u>IN</u> | | <u>FT</u> | <u>IN</u> |
|-----------|-----------|----------------------|-----------|-----------|
| 15 | | surface | 15 | |
| 2 | 9 | blue shale | 17 | 9 |
| 1 | 3 | coal | 19 | |
| 15 | | drab shale | 34 | |
| 5 | 4 | blue and black shale | 39 | 4 |
| | 8 | coal | 40 | |
| 23 | | shale and sandstone | 63 | |
| 7 | 11 | blue and black shale | 70 | 11 |
| | 6 | coal | 71 | 5 |
| 24 | 7 | shale and sandstone | 96 | |
| 11 | | sandstone with oil | 107 | |
| | 4 | coal | 107 | 4 |
| | 6 | soft black rash | 107 | 10 |
| | 2 | coal | 108 | |
| 1 | 4 | soft black rash | 109 | 4 |
| | 3 | coal | 109 | 7 |
| | 9 | blue clay | 110 | 4 |
| 1 | | drab clay | 111 | 4 |

Driller--L. L. Brown