

Company Workman Oil Co.

1-31-21 E
Sec. 1 T. 31 R. 21 E

Farm Mullin

No. 22

Loc.

County Crawford

Total Depth 247'


Comm.

Comp. Spud. June 1, 1919 ?

Shot or Treated

Contractor

Issued



Casing	
20 in.	10 in.
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

surface	2	
clay	8	
lime	15	
black shale	22	water
lime	38	
black shale	43	
light shale	120	
black shale	143	
lime	145	
black shale	146	
lime	147	
black shale	160	
light shale	165	
black shale	170	
lime	171	
light shale	207	good show of oil S.L. M.
brown sand	212	good show of oil fairly hard
dark brown sand	217	extra good show oil fairly hard
brown sand	222	good oil
brown sand	227	good oil
sandy shale	229	
black shale	235	
light shale	247	T. D.