

Sec. 19 Twp. 34S Rng. 18E Spot *SESE*

Formation Tested *APP*

Test No. *1*

State *KAN* Country *LACETTE*

Lease *WES* Well No. *1*

Date *July 7, 1967*



PHONE CA5-1261
POST OFFICE BOX 732
CUSHING, OKLAHOMA

Company *NAT'L Assoc. Petro. Co.* Address *504 Rte*

Charge to *"* Address *"*

Mail Charts to *"* No. Copies *3*

Extra Copies to *"* No. Copies *"*

Tested From *1191* To *1197* Total Depth *1197*

Tool Open—Hours *20* Minutes *20* Initial Shutin—Hours *X* Minutes *X* Final—Hours *X* Minutes *0*

Blow *Few Weak bubbles, then died*

Recovery *2' Mud*

Initial Flow Pressure *0* Final Flow Pressure *0*

Initial Bottom Hole Pressure *0* Final Bottom Hole Pressure *0*

Initial Hydrostatic Pressure *614* Final Hydrostatic Pressure *614*

Gas to Surface *No* Total Fluid *2'* Surface Pressure *0*

Hole Size *7 1/2* DP Size *3 1/2" 1F* Tool Joint *117 - 2 1/4" DC*

Mud Weight *9.2* Viscosity *42* Water Loss *?*

Extra Equipment *Jars* *110* Safety Joint *1* Dual Packers *1*

Operator Time *6 hrs* Price of Job *330.00*

INDIAN TESTING COMPANY shall not be liable for damage of any kind to the property of the one for whom a test is made or for any loss suffered or sustained directly or indirectly through the use of its equipment, or its statements or opinion concerning the results of any test. Tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made. All charges subject to 6% interest after 60 days from date of invoice. Any expense incurred for collection will be added to the original amount.

Company Representative *Joe S. M. Danah*

No. 1737

Tester *John S. M. Danah*