

Company - CHAMPLIN REFG. CO
Farm - Sutor No. 2

SEC. 22 T. 10 R. 20 W
SE SW NE
2310' fNL 1650' fEL NE $\frac{1}{4}$

Total Depth. 3835'

Comm. 11-5-44

Shot or Treated.


Contractor.

Issued. 3-31-45

Comp. 11-20-44

County. Rooks

KANSAS



Elevation. _____

Production. Dry

Figures Indicate Bottom of Formations.

shale & shells	0-190
shale	256
shale & shells	675
shale, sand & shells	1080
shale	1130
sand	1370
shale & red bed	1657
anhydrite	1695
red bed & shale	1900
shale, shells, salt	2065
salt & shale	2200
shale	2255
shale & shells	2315
shale & lime	2460
lime & shale	2515
lime	2555
lime & shale	2685
shale & lime	2875
shale	2920
shale & lime	2925
shale	3070
shale & lime	3145
shale	3210
lime & shale	3270
shale & lime	3340
lime	3640
lime & shale	3690
lime, shale & chert	3720
chert	3732
lime	3745
conglomerate & chert	3798
conglomerate, shale & chert	3825
lime & chert	3835
Total Depth	

Formation Tops:

Kansas City	3430
Simpson	3800
Arbuckle	3818