

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.  
412 Union National Bank Bldg, Wichita, Kansas.

48563

MARGAY OIL CORP.  
Bomis No. 2-B.


SEC 15 T. 11 R. 17W.  
NW SW SW

Total Depth. 3423 $\frac{1}{2}$   
Comm. 7-14-36 Comp. 8-22-36  
Shot or Treated.  
Contractor.  
Issued. 9-26-36

County. Ellis.

CASING.

15 $\frac{1}{8}$ " 65'  
10" 1108'  
65/8" 3409'



Elevation.

Production. Pot. 1671B.

Figures Indicate Bottom of Formations.

cellar	11	shale	2235
shale	59	broken lime	2263
blk foam and gravel	65	lime	2316
shale and lime shells	86	lime broken	2361
shale and shells	200	lime	2408
sticky shale	324	shale	2418
lime	339	lime	2496
shale sticky	385	lime hard	2508
red bed	415	shale and shells	2588
shale sticky	449	lime broken	2658
shale and shells	534	shale	2682
shale sticky	555	lime	2724
pyrites of iron	561	lime hard	2740
lime and shale	588	shale and lime shells	2806
shale sticky	640	lime	2968
sand and sand rock	750	lime hard	2988
lime	786	lime	3018
sticky red bed	854	lime hard	3023
red bed and shale	943	lime soft	3030
red bed	1010	lime	3048
red rock and shale	1045	lime hard	3075
red bed	1104	lime soft and showing oil	3077
lime	1108	lime hard	3082
anhydrite	1125	lime	3130
lime	1140	rod rock	3135
red rock	1405	broken lime	3202
shale	1460	lime hard	3233
salt	1667	lime	3259
shale and shells	1797	SLM corr. 3259 equals	3245
red rock	1815	lime	3248
lime	1835	rod rock and shale	3268
broken lime	1892	lime	3350
shale and shells	1984	rod rock and shale	3368
lime	2008	conglomerate	3400
red rock	2014	shale green	3408
lime	2196	lime	3409
broken lime	2220	lime	3421
		lime hard	3423 $\frac{1}{2}$
		Total Depth.	

Company Margay Oil Corp.

Farm Bemis

No. 2 B

Sec. 15 T. 11 R. 17W  
Loc. NW SW SW  
County Ellis

Total Depth 3423½


Comm. 7-14-36

Shot or Treated

Contractor

Issued

Comp. 8-22-36



Casing

20 in.		10 in	1108
15 1/2	65	8 1/4	
12 1/2		6 5/8	3409
13 3/8		5 3/16	

Elevation 1894

Production 1671 B.

Figures Indicate Bottom of Formation

Plotted Texas C