

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY
412 Union National Bank Bldg, Wichita, Kansas.

MARGAY OIL CORP.
Bemis No. 3-A

Plotted Texas CO.
SEC. 16 T. 11 R. 17W.
SW SE SE

Total Depth. 3333
Comm. 8-20-36 Comp. 9-16-36
Shot or Treated.
Contractor.
Issued. 12-12-36

County Ellis.

WASING.

15 1/2" 114'
10" 1026'
65/8" 3328'

DEC 12 1936



Elevation.

Production. Pot. 1665 B.

Figures Indicate Bottom of Formations.

cellar	11	lime and broken lime	1926
sand	16	broken lime	2017
slate and shells	114	lime	2100
slate and shells	204	broken lime	2123
shale hard shells	215	lime	2140
shale	230	red bed	2155
red bed sticky	263	lime broken	2206
lime	264	lime	2295
shale and shells	280	red rock shale and shells	2340
red rock and shells	345	shale and shells	2544
red rock	358	lime grey	2556
shale and shells	390	sticky shale	2569
sand and shells	412	lime	2605
sand	480	slate and shale	2640
pyrites iron	501	lime hard	2655
sand hard and iron shells	520	shale	2665
sand and shells	620	lime hard	2685
sand	681	shale and shells	2715
red rock and lime shells	750	sticky shale	2728
red bed sticky	784	shale and shells	2735
shale red	839	sticky shale	2745
red rock and shale	906	lime	2914
sticky shale and lime shells	951	lime hard	2929
shale sticky	1018	lime soft	2939
chalk	1021	lime	3009
lime	1026	lime hard	3034
anhydrite	1036	broken lime	3077
anhydrite and sand	1065	lime	3296
red bed	1185	conglomerate	3308
shale	1200	shale green	3314
shale and shells	1240	cored	3324
red bed	1295	sand with streaks of green shale	
shale shells and slate	1387	cored	3328
shale and shells	1405	lime	3333
red bed and salt	1560		
lime shells and red bed	1606		
shale and shells	1770		
lime	1806		
shale and shells	1816		
lime broken	1830		
red bed	1882		

Total Depth.