

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.
412 Union National Bank Bldg, Wichita, Kansas.


CHAMPLIN REFINING CO.
Hadley "D" No. 11

SEC. 17 T. 11 R. 17 W.
CN $\frac{1}{2}$ SW SW
990' N SL 660' E WL SW $\frac{1}{4}$

SECOND HOLE.

Total Depth. 3480
Comm. 5-1-41 Comp. 9- 3-41
Shot or Treated.
Contractor.
Issued. 4-4-42

County. Ellis.



Rotary

CASING.

85/8" 1180' cemented.
4 $\frac{1}{2}$ " 3466' 11" cemented.

Elevation.

Production. Pot. 2778 B.

Figures Indicate Bottom of Formations.

shale and shells	315-	570
pyrite		605 ✓
shale		825
shale and shells		1000
red bed and shale		1174
anhydrite		1180
anhydrite		1210
red bed and shale		1388
shale		1414
shale and shells		1545
shale and salt		1658
shale and shells		1792
broken lime and shale		1866
lime shells and shale		1925
lime and shale		3050
lime		3107
shale and lime		3185
lime		3435
conglomerate		3450
lime and shale		3458
shale		3466
lime Arbuckle strong odor		3480

Total Depth. 3480 ?

Note - From 315 to 1380 the log is as
for the first hole. Below 1380
new hole was drilled in the
directional work on this hole.

Log for directionally-drilled
second hole at this location
(Hole deflected northeast)