

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.
412 Union National Bank Bldg., Wichita, Kansas.

G. E. Jamison

CHAMPLIN REFINING CO.
Meier No. 2-A.

SEC. 36 T. 11 R. 18W.
SE NE SW
990' S of N.L. 330' W of E.L.
SW $\frac{1}{4}$


OCT 30 1937

Total Depth. 3574
Comm. 8-26-37 Comp. 9-14-37
Shot or Treated.
Contractor.
Issued. 10-30-37

County Ellis.

OCT 30 1937

Rotary 3566
Cable 3574



Elevation.

CASING.

95/8" 1122' 7" 3566'

Production. Pot. 1154.28 B.

Figures Indicate Bottom of Formations.

surface hole	70
shale	440
sand and shale	698
shale	800
sand	940
red rock	955
sand	980
red bed	1050
sand	1058
red bed	1100
sand	1115
red bed	1122
red rock	1272
anhydrite	1340
red rock	1422
shale and shells	1665
salt	1695
shale	1880
shale and shells	1985
broken lime	2036
shale and lime	2133
broken lime	2253
lime and shale	2316
broken lime	2426
lime and shale	2492
shale and shells	2593
broken lime	2640
shale and shells	2646
lime and shale	2705
broken lime	2762
lime and shale	2846
lime	2897
broken lime	2993
lime	3025
broken lime	3070
lime	3533
chert and Var. shale	3555
coring	3559
coring lime	3564
chert and Var. shale	3574
Total Depth.	
SILICEOUS LIME	3567-3574