

MILLER-DONELSON TESTING CO.

P. O. BOX 547

PHONE 3370

GREAT BEND, KANSAS

DATE

file
March 18, 1956

COMPANY

K & C Drilling Inc.

ADDRESS

1006 Central Bldg Wichita Kansas

LEASE

Madden

WELL NO.

1

COUNTY

Dugo

DEPTH

3833

PACKER SET

3804'

TEST NO.

1

SUCCESSFUL TEST NO.

✓

MIS-RUN NO.

✓

TOOL JT.

4 1/2

REMARKS:

open by press

TOOL OPEN HR.

MIN.

30

SHUT-IN

15

MIN.

SIZE HOLE

7/8

BLOW

weak blow for 5 min

RECOVERY

10' Roly Mod. w/ 5 specks of Dead Oil -

INITIAL FLOW PRESSURE

0

FINAL FLOW PRESSURE

0

BOTTOM HOLE PRESSURE

*140**

OPERATOR TIME

10

EXTRA EQUIPMENT

✓

PRICE OF JOB

\$210.00

FIELD ORDER NO.

✓

MILLER-DONELSON TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE ONE FOR WHOM A TEST IS MADE, OR FOR ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH THE USE OF ITS EQUIPMENT, OR ITS STATEMENTS OR OPINION CONCERNING THE RESULTS OF ANY TEST. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT COST BY THE PARTY FOR WHOM THE TEST IS MADE.

APPROVED BY

W. L. Brumgar

OUR REPRESENTATIVE

E. J. Bingham
H. L. Budig

TEST N°

1223

Company K & E Drilling Co

Test No. 1 Ticket No. 1223

IF 0 FF 0 BHP 140*

Hydrostatic 2130*

MILLER-DONELSON TESTING CO.

P. O. BOX 547

GREAT BEND, KANSAS

GEORGE MILLER
PHONE 3370
GREAT BEND, KANSAS

JIM DONELSON
PHONE 4-2717
HAYS, KANSAS

TEST NO. 1

TICKET NO. 1223

COMPANY K. & E. Drilling, Inc. WELL Madden #1

DEPTH 3833' BOTTOM HOLE MUD RPSURE 2130 #


CHOKES - TOP 1/2" BOTTOM 1/2" SURFACE PRESSURE 0

BOTTOM PRESSURE 0 IFP 0 FFP 0 SHUT-IN 140 #

TESTED FROM 3804' TO 3833' DATE 3-18-54

RECOVERY:

10' rot. mud w/ specks of dead oil



MILLER-DONELSON TESTING CO.

P. O. BOX 547

GREAT BEND, KANSAS

GEORGE MILLER
PHONE 3370
GREAT BEND, KANSAS

JIM DONELSON
PHONE 4-2717
HAYS, KANSAS

TEST NO. 1

TICKET NO. 1223

COMPANY K. & E. Drilling, Inc. WELL Madden #1
DEPTH 3833' BOTTOM HOLE MUD PRESSURE 2130 #
CHOKES - TOP 1/2" BOTTOM 1/2" SURFACE PRESSURE 0
BOTTOM PRESSURE 0 IFP 0 FFP 0 SHUT-IN 140 #
TESTED FROM 3804' TO 3833' DATE 3-18-54

RECOVERY:

10' rot. mud w/ specks of dead oil

