

A.V. STAAB #5
 E 1/2 NW 1/4 Section 11-12S-18W
 Ellis Co., Kansas
FORMATION RECORD

cc: File
 Acctg. Dept.
 Field
 Well Log Bureau

11-12-18W

<u>FORMATION</u>	<u>THICKNESS</u>	<u>REMARKS</u>
Cellar	8	
Clay	15	
Shale, Shells	630	
Shale	865	
Lime	885	
Sand	1035	
Hard Sand	1030	
Sand	1145	
Red Bed, Shells	1364	
Anhydrite	1378	
Lime	1390	
Anhydrite	1425	
Red Bed, Shells	1500	
Red Rock, Salt	1670	
Salt	1855	
Salt, Shale	1965	
Lime, Shale	2000	
Lime	2590	
Broken Lime	2660	
Lime	2735	
Lime, Shale, Shells	2805	
Broken Lime	2854	
Shale, Shells	2970	
Lime	2995	
Shale, Shells	3060	
Shale	3070	
Lime	3157	SHT at 3100-OK
Broken Lime	3200	
Lime	3225	
Dolomitic Lime	3240	
Hard Lime	3274	
Lime	3405	
Broken Lime	3410	
Shale	3415	
Broken Lime	3420	
Lime	3605	
Red Shale	3625	
Lime	3650	
Cored Lime	3655	

SE SE NW

3435
 2129

 1306

3785
 2120

 1256
 15

 -1241

3649
 2129

 1520

3415
 2129

 1286

3470
 2129

 1341

RECEIVED
 STATE CORPORATION COMMISSION
 MAY 10 1985
 CONSERVATION DIVISION
 Wichita, Kansas