



# TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED  
FEB 15 2010

## Test Ticket

No. 37195 13898

Well Name & No. Marley L-7 BY: \_\_\_\_\_ Test No. 1 Date 2/11/10  
 Company Martin Drilling Co. Elevation 2534 KB 2529 GL \_\_\_\_\_  
 Address 250 N Water St E 300 Wichita KS 67202  
 Co. Rep / Geo. Paul Gangelman Rig Martin #16  
 Location: Sec. 7 Twp. 12S Rge. 24w Co. Trego State KS

Interval Tested 4058-4076 Zone Tested LAC #2  
 Anchor Length 18 Drill Pipe Run \_\_\_\_\_ Mud Wt. 8.9  
 Top Packer Depth 4053 Drill Collars Run 30 Vis 59  
 Bottom Packer Depth 4058 Wt. Pipe Run \_\_\_\_\_ WL 6.4  
 Total Depth 4076 Chlorides 4600 ppm System LCM \_\_\_\_\_  
 Blow Description IF-1/4 in blow  
ISI-NO blow  
FF-Very weak surface blow  
FSI-NO blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>1</u>	<u>oil spotted mud</u>				
_____	_____				
_____	_____				
_____	_____				
_____	_____				

Rec Total 1 BHT 109 Gravity \_\_\_\_\_ API RW \_\_\_\_\_ @ \_\_\_\_\_ °F Chlorides \_\_\_\_\_ ppm

(A) Initial Hydrostatic 1957  Test 1150 T-On Location 1:30  
 (B) First Initial Flow 12  Jars \_\_\_\_\_ T-Started 3:14  
 (C) First Final Flow 13  Safety Joint 75 T-Open 6:40  
 (D) Initial Shut-In 23  Circ Sub \_\_\_\_\_ T-Pulled 9:40  
 (E) Second Initial Flow 13  Hourly Standby \_\_\_\_\_ T-Out 11:03  
 (F) Second Final Flow 13  Mileage 44x2 88 Comments \_\_\_\_\_  
 (G) Final Shut-In 20  Sampler \_\_\_\_\_  
 (H) Final Hydrostatic 1957  Straddle \_\_\_\_\_  
 Shale Packer \_\_\_\_\_  Ruined Shale Packer \_\_\_\_\_  
 Extra Packer \_\_\_\_\_  Ruined Packer \_\_\_\_\_  
 Extra Recorder \_\_\_\_\_  Extra Copies (8) 3-15  
 Initial Open 30  Day Standby \_\_\_\_\_ Sub Total 0 15  
 Initial Shut-In 60  Accessibility \_\_\_\_\_ Total 1328  
 Final Flow 30  
 Final Shut-In 60  
 Sub Total 1313

Approved By Paul Gangelman Our Representative Butt Diner  
 Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test. tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.