


DREILING OIL, INC.

Victoria, Kansas 67671

API# 15-109-20,025

7-12-36W



Dreiling Oil, Inc. WELL LOG
Rt. #2

Company Victoria, Kansas 67671

Farm Medford No. 1

Total Depth 4,707'

Comm. 7-30-73 Comp. 8-10-73

Contractor Dreiling Oil, Inc.
Rt. #2
Victoria, Kansas 67671

Sec. 7 Twp. 12 Rng. 36 W

Location C ^{NE} SW
C NE SE - Intent.

County Logan

Elevation: 3124 K. B.

3121 D. F.

3119 G. R.

Casing Record

Cement Record

Production:

169' - 8 5/8"

135 sacks cement

D & A

Figures Indicate Bottom of Formations

0'	25'	Top Soil
25'	169'	Shale
169'	1754'	Shale
1754'	1916'	Hard Sand
1816'	1900'	Shale
1900'	1960'	Blain Anhydrite
1960'	2160'	Shale and Sand
2160'	2691'	Shale
2691'	2731'	Anhydrite
2731'	2805'	Shale & Hard Sand
2805'	3485'	Shale and Lime
3485'	3795'	Lime
3795'	3895'	Lime & Shale
3895'	4665'	Lime
4665'	4707'	Miss.
4707'	T.D.	

SMP TOPS

TOP	3568	Mrm	4545
Heeb	3848	Cher	4398
Tor	3873	Miss	4650
Lans	3892	TD	4707
BKC	4230		

STATE OF KANSAS)

)ss

COUNTY OF ELLIS)

I, Joe Hess, Secretary Treasurer, of Dreiling Oil, Inc. upon oath states that the above and foregoing is a true and correct copy from the Daily Drilling Report from the Medford #1.

Joe Hess
JOE HESS

Subscribed and sworn to before me this 15th day of August, 1973.



Cilia Basco