PETROLEUM GEOLOGIST DONALD J. MELLAND

401 Peoples Bank Building . Post Office Box 783 . McPherson, Kansas 67460 Office (316) 241-7907 Residence (316) 241-4582

GEOLOGICAL REPORT

Excalibur Production Co., Inc. Gillmore "B" # 1 130' N SE SE SE. Sec. 17-15-1W Field: Gillmore Ext. Saline County, Kansas

March 17, 1986 Elevation: 1277 KB Comm: 3/10/96; Comp: 3/14/96 Casing: 8-5/8" @ 200'/130sx.

FORMATION TOPS

Lansing Mississippian

RTD

2038 (-761) 2683 (-1406) 2722 (-1445)

Cores: None

Drill Stem Tests: None

Electrical Logs: None

Gas Detector: None

3 feet above ground level. Measurements: Were taken from kelly bushing,

FORMATION SUMMARY

MISSISS IPPIAN

2683-2697 Limestone: white to buff coarsely crystalline, chalky in part, glauconitic, dense, no shows of oil.

2697-2700 Limestone: buff, coarsely crystalline, dolomitic, poor porosity, trace of heavy black oil and scumy oil, questionable to very faint odor. This zone does not warrant testing.

> Control Carlow Control Control MAR 1 9 1980

> > CONSERVATION DIVISION Wichita, Kansas

Gillmore "B" # 1

Geological Report

Page 2

2700-2722 Dolomite: buff to tan, finely to medium crystalline, slightly glauconitic, poor and fair porosity throughout, no shows of oil,

RECOMMENDATIONS

Since there were no commercial shows of oil in this well, it was recommended that it be plugged.

Respectfully submitted,

Donald J. Melland

DJM/f

