

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

January 18, 1927.

E. I. THOMPSON'S

F. J. LILAK No. 1.

Location - Center of NW 1/4 of the SE 1/4
of Section 22, Township 18 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Log to date:

From	To	
0	30	Clay yellow
30	80	Slate black
80	149	Slate blue
149	151	Slate blue iron
151	170	Slate gray
170	190	Clay yellow
190	206	Clay yellow
206	210	Sand gray - 8 barrels water per hour.
210	220	Clay yellow
220	225	Red rock
225	260	Shale gray
260	270	Shale gray
270	292	Shale blue
292	306	Sand gray
306	315	Slate blue
315	320	Lime
320	330	Slate blue
330	380	Slate blue
380	386	Slate blue
386	400	Shale blue
400	423	Sandy lime
423	440	Slate blue
440	443	Lime gray
443	447	Slate blue
447	455	Lime gray
455	505	Sand gray
505	530	Slate blue
530	535	Slate gray
535	580	Red rock
580	600	Red rock

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

January 26, 1927.

E. I. THOMPSON'S

F. J. LILAK No. 1.

Location - Center of NW 1/4 of the SE 1/4 of
Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
600	700	Red Rock
700	705	Red Rock
705	720	Blue Mud
720	730	Blue Mud
730	745	Lime black hard
745	750	Blue Mud
750	755	Red Rock
755	763	Red Rock soft
763	765	Magnitite
765	780	Lime brown
780	800	Red Rock

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

February 1, 1927.

E. I. THOMPSON'S

F. J. LILAK No. 1,
Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
800	805	Red Rock
805	810	Red Rock
810	815	Red Rock
815	840	Red Rock

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

February 8, 1927.

E. I. THOMPSON'S

P. J. LILAK No. 1,
Location- Center of the NW 1/4 of the SE 1/4
of Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
840	870	Red Rock
870	930	Red Rock
930	990	Slate gray soft
990	1030	Red Rock soft
1030	1035	Glassy Lime
1035	1045	Slate blue
1045	1140	Slate blue
1140	1155	Slate blue
1155	1240	Salt
1240	1350	Salt
1350	1370	Salt
1370	1380	Slate
1380	1391	Shale
1391	1400	Lime
1400	1407	Shale
1407	1409	Lime
1409	1415	Slate
1415	1430	Lime
1430	1435	Slate
1435	1455	Lime
1455	1465	Lime white
1465	1470	Slate gray
1470	1475	Broken Lime
1475	1483	Lime white
1483	1486	Shale blue
1486	1510	Lime white
1510	1520	Red Rock
1520	1540	Lime white
1540	1567	Slate blue soft
1567	1577	Lime gray hard
1577	1590	Slate blue soft
1590	1600	Lime black hard
1600	1620	Red Rock soft.

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

February 15, 1927.

E. I. THOMPSON'S

F. J. LILAK No. 1,

Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
1620	1625	Red Rock
1625	1630	Slate blue soft
1630	1650	Lime dark hard
1650	1665	Slate blue soft
1665	1720	Lime dark hard
1720	1765	Lime white hard
1765	1770	Slate blue soft
1770	1775	Red Rock soft
1775	1800	Lime white hard
1800	1825	Lime white hard
1825	1855	Slate blue soft
1855	1865	Red Rock soft
1865	1870	Lime white hard
1870	1890	Red Rock soft
1890	1900	Lime white hard
1900	1910	Slate blue soft.

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

February 22, 1927.

E. I. THOMPSON'S

F. J. LILAK No. 1,

Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
1910	1915	Lime white hard
1915	1925	Red Rock soft
1925	1929	Blue Shale soft
1929	1934	Lime white hard
1934	1940	Red Rock soft
1940	1945	Lime white hard
1945	1965	Slate blue soft
1965	1975	Lime white hard
1975	1985	Red Rock soft
1985	2005	Lime gray hard.

E. I. THOMPSON
1014 DANIEL BUILDING
TULSA, OKLAHOMA

March 2, 1927

E.I. Thompson's

F.J.Lilak No.1.

Location - Center of the NW $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Section 22,
Township 15 S, Range 11 W.

Russell County Kansas

Continuation of Log:

From	To	
2005	2020	Shale blue soft
2020	2040	Lime white hard
2040	2065	Slate blue soft
2065	2075	Red Rock soft
2075	2085	Lime gray hard
2085	2100	Slate blue

Under-reaming 10 inch to 2100 ft.

E. I. THOMPSON

1014 DANIEL BUILDING

TULSA, OKLAHOMA

March 9, 1927

E.I. Thompson's

F.J. Lilak No.1

Location - Center of the NW $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Section

22, Township 15 S, Range 11 W.

Russell County Kansas

CONTINUATION OF LOG:

From	To	
2100	2110	Blue Slate soft
2110	2130	White Lime hard
2130	2247	Blue slate soft
2247	2250	Red rock soft
2250	2265	Blue slate soft
2265	2275	Gray lime hard
2275	2280	Blue slate soft

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

March 22, 1937.

E. I. THOMPSON'S

P. J. LILAK No. 1,

Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Twp. 13 S. Range 11 W,
MUSKIE COUNTY, KANSAS.

Continuation of Log:

From	to	
2290	2310	Slate blue soft
2310	2320	Red Rock soft
2320	2345	Slate blue soft
2345	2360	Slate blue soft

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

March 20, 1927.

E. I. THOMPSON'S

P. J. LEAK No. 1.

Location - Center of the NW 1/4 of the SE 1/4
of Section 28, Township 15 N, Range 11 W,
RUSSELL COUNTY, KANSAS.

-Continuation of Log:

From	to	
2345	2360	Slate blue soft
2360	2370	Slate blue soft
2370	2375	Blue slate soft
2375	2377	Lime
2377	2380	Lime white hard
2380	2395	Lime white hard
2395	2397	Lime white hard
2397	2407	Sand gray soft - Hole full water
2407	2425	Slate blue soft
2425	2430	Slate blue soft.

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

April 5, 1927.

E. I. THOMPSON'S

F. J. LILAK No. 1,

Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
2430	2435	Slate blue soft
2435	2445	Lime white hard
2445	2475	Slate blue soft
2475	2495	Slate blue - bailing water.

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

April 19, 1927

E.I. Thompson's

F.J. Lilak # 1

Location - Center of the NW $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Section 22,

T 15S, R 11W, Russell County, Kansas

From	To	
2495	2520	Blue Slate
2520	2590	Blue Shale
2590	2600	White Lime
2600	2610	Blue Slate
2610	2615	White Lime
2615	2645	Blue Slate
2645	2650	White Lime
2650	2658	Blue Slate
2658	2735	Gray Lime
2735	2740	Sandy Lime 2 ss. W
2740	2835	Gray Lime
2835	2845	Sandy Lime 1 B.W. 2835 - 40
2845	2875	White Lime

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

April 23, 1927.

E. I. THOMPSON'S

P. J. LILAE No. 1.

Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Township 10 N, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
2876	2897	Lime
2897	2912	Slate blue
2912	2928	Chat
2928	2938	Red Rock

E. I. THOMPSON
1014 DANIEL BUILDING
TULSA, OKLAHOMA

May 3, 1927.

E. I. THOMPSON'S

P. J. LILAK No. 1,
Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
2932	2953	Red Rock soft
2933	2990	Shale blue soft
2990	2992	Blue Slate soft
2992	2996	Lime medium
2996	3000	Slate blue soft
3000	3020	Lime white hard
3020	3024	Lime medium
3024	3027	Slate blue soft
3027	3077	Lime white hard

Steel Line Measurement - 3091'.

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

May 17, 1927.

E. I. THOMPSON'S

F. J. LILAN No. 1,

Location - Center of the NW 1/4 of the SE 1/4
of Section 22, Township 15 S, Range 11 W,
RUSSELL COUNTY, KANSAS.

Shut down curing titles.

E. I. THOMPSON

1014 DANIEL BUILDING
TULSA, OKLAHOMA

August 2, 1927.

Land

E. I. THOMPSON'S

F. J. LEAK No. 1,

Location - Center of the NW 1/4 of the SE 1/4
of Sec. 22, Twp. 15 S, Range 11 E,
RUSSELL COUNTY, KANSAS.

Continuation of Log:

From	to	
3315	3325	Red Rock
3325	3340	Lime white hard
3340	3345	Lime sandy - hole full water and oil.
3345	3352	Lime sandy
3352	3360	Various formations red
3360	3365	Broken Lime
3365	3375	Red Rock
3375	3380	Lime