

Total Depth. 4910
Comm. 2-23-37 Comp. 5-12-37
Shot or Treated.
Contractor. Rose Spring Drlg. Co.
Issued. 7-24-37

County Logan.

CASING.

JUL 24 1937



12 1/2" 55'
4" 4592'

Elevation. 3045

Production. DRY

Figures Indicate Bottom of Formations.

RIG SKIDDED A FEW FEET FROM NUMBER 1

shale	450
shale shells	1165
broken lime	1270
shale and shells	1355
limo	1375
shale and shells	1475
shale and lime	1550
lime	1565
shale shells	1670
red rock	1820
red rock and lime	2220
shale and lime	2270
limo red rock	2340
shale and lime	2540
limo	2595
shale and limo	2720
red rock and lime	2750
limo	2815
shale and limo	2905
limo	3040
shale and lime	3130
lime	3230
lime and shale	3265
lime	3375
shells	3405
limo	3480
shale and limo	3525
limo	3630
broken limo	3675
limo and shale	3755
lime	3790
lime and shale	3835
limo	3855
shale and limo	3940
lime	3960
lime and shale	4000
limo	4465
broken limo	4505
lime and shale	4550
lime	4592
cored 4592-97	
cored 4597-4600	
lime shale breaks	4605
lime	4685
lime shale breaks	4710
limo	4735
lime and shale	4810
lime	4825

shale and lime	4895
lime	4910
Total Depth.	