



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 38601 14167

APR 19 2010

Well Name & No. KK #1 Test No. 1 Date 4.19.10
 Company Bennett & Schulte Oil Company Elevation 1841 KB 1834 GL
 Address PO Box 329 Russell KS 67465
 Co. Rep / Geo. Brad Hutch Rig Royal Drilling Rig #2
 Location: Sec. Le Twp. 16 S Rge. 10 W Co. Ellsworth State KS

Interval Tested 3280-3345 Zone Tested ARBUCKLE
 Anchor Length 605 Drill Pipe Run 3284 Mud Wt. 9.5
 Top Packer Depth 3275 Drill Collars Run 0 Vis 52
 Bottom Packer Depth 3280 Wt. Pipe Run 0 WL 8.8
 Total Depth 3345 Chlorides 4000 ppm System LCM 1/2 #

Blow Description IFP - Strong Blow BOB IN 30 sec
ISF - Dead NO Blow Back
FFP - Strong Blow BOB IN 30 sec
FSF - Dead NO Blow Back

Rec	Feet of	%gas	%oil	%water	%mud
<u>448</u>	<u>Mud with A Scum of oil</u>				
<u>320</u>	<u>WM with A Scum of oil</u>			<u>70%</u>	<u>30%</u>
<u>1528</u>	<u>WM with A Scum of oil</u>			<u>90%</u>	<u>10%</u>
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 2336' BHT _____ Gravity _____ API RW 0.5 @ 41 °F Chlorides 24000 ppm

(A) Initial Hydrostatic 1700 Test 1125 T-On Location 1:09
 (B) First Initial Flow 634 Jars _____ T-Started 1:59
 (C) First Final Flow 875 Safety Joint _____ T-Open 3:15
 (D) Initial Shut-In 1048 Circ Sub _____ T-Pulled 4:15
 (E) Second Initial Flow 935 Hourly Standby _____ T-Out 7:33
 (F) Second Final Flow 1026 Mileage 128 RT 160 Comments _____
 (G) Final Shut-In 1069 Sampler _____
 (H) Final Hydrostatic 1631 Straddle _____

Initial Open 15 Ruined Shale Packer _____
 Initial Shut-In 15 Ruined Packer _____
 Final Flow 15 Extra Copies _____
 Final Shut-In 15 Day Standby _____ Sub Total 0
 Accessibility _____ Total 1288
 Sub Total 1288

Approved By _____ Our Representative Jeff Brown

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.