

SINCLAIR PRAIRIE OIL CO.
Mary Prusa No. 3

20-16-11W
SEC. 20 T. 16 R. 11 W.
NE 1/4 SE
330' fr Nth and 330' fr E. L.
SE 1/4

Total Depth. 3293
Comm. 9-2-39 Comp. 9-18-39
Shot or Treated.
Contractor. Harbar Drlg. Co.
Issued. 10-21-39

County Barton.

Rotary 3286
Cable 3293

CASING.

103/4" 92'
7" 3284'

Elevation.

Production. Pot. 117 B.
Nat. Temp. Pot.

Figures Indicate Bottom of Formations.

lime rock and shalo	40	shalo
shale and sholls	92	limo
sholls and shalo	325	
water sand	390	
shale	535	
red bod shalo	690	
anhydrite shalo	725	
anhydrite	740	
shalo and sholls	1150	
salt and shalo	1350	
shalo and sholls	1430	
limo	1490	
shale and sholls	1645	
limo	1700	
shalo	1720	
limo	1745	
shalo and sholls	1765	
sdv limo and shalo	1800	
shalo and sholls	1840	
limo	1855	
broken limo and shalo	1910	
limo	1990	
broken limo and shalo	2100	
shalo limo sholls	2170	
shalo and sholls	2430	
limo	2460	
shalo limo sholls	2570	
shalo blk	2580	
shalo and limo	2648	
shalo and sholls	2685	
sdv limo	2695	
limo	2710	
limo and shalo	2725	
broken limo	2735	
limo	2760	
broken limo sand	2780	
limo	2915	
shalo	2930	
limo soft	2970	
shalo limo	3005	
limo	3260	

3283 Top Arbuckle 3284
3293 Total Depth.