

COMMUNITY-CARTER ET AL.
Elizabeth No. 2

SEC. 34 T. 17 R. 9W.
CEL NE
1320' NL 440' EI:

Total Depth. 3178
Comm. 1-1-37 Comp. 1-25-37
Shot or Treated.
Contractor. Parker Drlg Co.
Issued. 2-13-37

County Ellsworth.



CASING.

10 3/4" 208' 7" 3171'

Elevation.

Production. Pot. 1020 B.

Figures Indicate Bottom of Formations.

cellar	7	
shale and shells	165	
clay	175	
broken lime	210	
shale and shells	545	
shale and shells	870	
salt and shale	897	
salt and shells	975	
shale and shells	1205	
lime	1220	
shale and shells	1305	
broken lime	1325	
shale and shells	1495	
sand	1525	
broken lime	1539	
broken lime	1554	
shale and shells	1608	
lime	1620	
shale and shells	1820	
lime	1828	
broken lime	1848	
shale and shells	1950	
shale and shells	2210	
broken lime	2260	
shale and shells	2439	
shale	2450	
broken lime	2498	
lime	2760	
shale and shells	2832	
shale and broken lime	2850	
limo	3136	
broken lime & shale	3158	
shale	3161	
conglomerate and green shale	3169	
lime	3178	2800' oil
Total Depth.		