WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.
412 Union National Bank Bldg, Wichita, Kansas.

24-19-12W

STELBAR OIL CORPORATION ET AL
Berscheidt No. 1

SEC. 25 T. 19 R. 12 W.
SW NW NW

Total Depth. 3401
Comm. 3-3-42 Comp. 3-24-42
Shot or Treated.
Contractor. Hannum Drilling Co. Inc.
Issued. 4-11-42

County Barton.



CASING.

8 5/8" 175' cemented.
5 1/2" 3372' cemented.

Elevation.

Production. DRY.

Figures Indicate Bottom of Formations.

surface soil	16
sand	70
clay	145
broken lime	175
broken lime and pyrite	200
shale and shells	305
red bed	587
anhydrite	658
shale and shells	760
red bed, shale and shells	885
broken lime and shale	995
shale and salt	1205
shale and shells	1240
shale and shells	1342
anhydrite	1480
broken sdy lime	1740
sand and lime	1800
broken lime	1905
broken sdy lime	2050
broken lime and shale	2155
broken sdy lime and shale	2290
broken sdy lime and shale	2430
shale and shells	2649
lime	2960
shale and lime	3040
shale	3101
lime (derrick floor Meas)	3165
lime	3321
broken lime	3350
shale	3359
conglomerate	3363
shale	3373
dolomite	3379
cored, full Rec. 3373-75	
RUST 3379-	3378 DFM
dolomite	3401
Total Depth.	

Top Lansing	3101
Arbuckle dolomite	3372