

P₁

Ind

2-20-25W

ROTARY DRILLING LOG

COMPANY: Pickrell Drilling Company
205 Litwin Building, 110 N. Market
Wichita, KS 67202

Rotary Drilling Commenced 10-31-80

LOCATION: Fehrenbach 'E'
C NW NE, Sec. 2-20S-25W
Ness County, Kansas

Rotary Drilling Completed 11-10-80

CONTRACTOR: **PICKRELL DRILLING COMPANY**
Wichita, Kansas

CASING RECORD: Spud date 10-31-80, surface pipe 8 5/8", Depth 583'KB, Cement 275sx.

*State Geological Survey
WICHITA BRANCH*

LOG

(Figures indicate bottom of formation — measurements from top of rotary bushing.)

Top Soil and Clay	35
Postrock	55
Shale and Sand	679
Shale and Red Beds	1150
Sand	1360
Shale and Sand Stringers	1625
Shale	1671
Anhy at Shale	1935
Shale	2130
Shale and Lime Stringers	2485
Lime and Shale	2728
Lime	2865
Lime and Shale	4390
Lime and Shale	4477
Dolomite	4485

The undersigned, C. W. Sebitts, Attorney-in-Fact for PICKRELL DRILLING COMPANY, hereby certifies in behalf of said Company, that the above is a true and correct log of the formation encountered in drilling the above well as reflected by the Daily Drilling Reports.

PICKRELL DRILLING COMPANY