



**TRILOBITE
TESTING INC.**

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED

JUN 16 2010

Test Ticket

NO. 38265 14386

Well Name & No. Garden City Company 6-18 Test No. 1 Date 6-12-10
 Company Lebsack Oil Production Elevation 2908 KB 2897 GL
 Address PO Box 489 Hays KS 67601
 Co. Rep / Geo. Wayne Lebsack Rig Sterling #2
 Location: Sec. 18 Twp. 22 Rge. 33W Co. Finney State KS

Interval Tested 4430-4463 Zone Tested Morrow
 Anchor Length 36' Drill Pipe Run 4185 Mud Wt. 9.4
 Top Packer Depth 4425 Drill Collars Run 249 Vis 50
 Bottom Packer Depth 4430 Wt. Pipe Run 0 WL 8.0
 Total Depth 4463 Chlorides 1600 ppm System LCM 3

Blow Description IF: Built to 1" Blow
IS: No Return Blow
FF: Surface Blow
FS: No Return Blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>100</u>	<u>MWDs</u>			<u>100</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 100 BHT 114 Gravity 1225.00 API RW 250.00 @ 75.00 °F Chlorides 1600 ppm
 (A) Initial Hydrostatic 2268 ☒ Test
 (B) First Initial Flow 22 ☒ Jars
 (C) First Final Flow 48 ☒ Safety Joint
 (D) Initial Shut-In 694 ☒ Circ Sub NL
 (E) Second Initial Flow 57 ☐ Hourly Standby
 (F) Second Final Flow 80 ☒ Mileage 60 RT 75.00
 (G) Final Shut-In 700 ☐ Sampler
 (H) Final Hydrostatic 2298 ☐ Straddle

T-On Location 12:00 Am
 T-Started 04:35
 T-Open 08:15
 T-Pulled 10:45
 T-Out 13:52

Comments

Initial Open 30
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 60

☐ Ruined Shale Packer
☐ Ruined Packer
☐ Extra Copies
 Sub Total 8
 Total 1625-
 Sub Total 1625-

Approved By

Our Representative

TriLOBITE TESTING Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.