


WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.  
412 Union National Bank Bldg, Wichita, Kansas.

E.J. SHAFFER  
Saylor No. 1.

SEC. 17 T. 23 R. 3W.  
CWL SW SW

Total Depth. 3366  
Comm. 6-15-40 Comp. 7-15-40  
Shot or treated  
Contractor.  
Issued 8-24-40

County Harvey.



CASING.

103/4" 279'  
7" 3303.21

Elevation.

Production. Pot. 590 B.

Figures Indicate Bottom of Formations.

|                              |      |                      |         |
|------------------------------|------|----------------------|---------|
| sand and shale streaks       | 225  | lime porous          | 2913    |
| lime shells red bed& shale   | 255  | lime and shalo       | 2930    |
| lime shells and shale        | 279  | limo                 | 2979    |
| lime shells and shale        | 335  | shalo                | 2995    |
| shale                        | 492  | lime and shalo       | 3060    |
| sdv lime                     | 550  | limo                 | 3080    |
| lime and shale               | 578  | lime and shale       | 3115    |
| broken lime & shale          | 810  | shale & lime streaks | 3185    |
| shale and shells             | 840  | VC shale             | 3230    |
| broken lime and shale        | 965  | conglomerate         | 3250    |
| lime hard and shale          | 975  | chat                 | 3255    |
| shale red & blue & lime      | 990  | limo and shalo       | 3282    |
| 990 equals 1022 S.L. M.Corr. |      | Porous lime (Gas)    | 3288    |
| lime and shale               | 1440 | limo Rotary T.D.     | 3337-5" |
| shale and shells             | 1587 | limo                 | 3348    |
| broken limo                  | 1600 | chat                 | 3366    |
| shalo                        | 1635 |                      |         |
| broken limo and shale        | 1680 | Total Depth.         |         |
| shalo                        | 1946 |                      |         |
| broken limo                  | 1960 |                      |         |
| shale and limo               | 1999 |                      |         |
| limo                         | 2024 |                      |         |
| lime and shale               | 2100 |                      |         |
| shale and lime shells        | 2143 |                      |         |
| limo                         | 2167 |                      |         |
| lime and shale               | 2194 |                      |         |
| limo                         | 2204 |                      |         |
| shale                        | 2215 |                      |         |
| lime and shale               | 2330 |                      |         |
| shalo and limo               | 2385 |                      |         |
| shalo                        | 2500 |                      |         |
| shalo and shells             | 2545 |                      |         |
| broken limo                  | 2563 |                      |         |
| lime hard                    | 2570 |                      |         |
| shalo and limo               | 2579 |                      |         |
| broken limo and shalo        | 2590 |                      |         |
| lime cherty                  | 2636 |                      |         |
| shalo                        | 2690 |                      |         |
| limo                         | 2766 |                      |         |
| porous limo                  | 2775 |                      |         |
| lime and shalo               | 2782 |                      |         |
| lime hard                    | 2794 |                      |         |
| shalo                        | 2800 |                      |         |
| limo                         | 2890 |                      |         |
| shalo                        | 2903 |                      |         |