

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.
412 Union National Bank Bldg, Wichita, Kansas.

OLSON OIL CO.
Murphy No. 1.

SEC. 30 T. 23 R. 3W.
NW 1/4 SE

Total Depth 3361.
Comm. 5-13-37 Comp. 6-12-37
Shot or Treated.
Contractor.
Issued. 7-10-37

County Harvey.



CASING.

12 1/2" 265'
7" 3287'

Elevation.

Production. Pot. 454 B.

Figures Indicate Bottom of Formations.

clay and sand	120	shale	2675
shale and sholls	265	broken limo	2706
shalo	435	lime	2724
shale and shells	572	broken lime	2785
shale and sholls	901	sdv shalo	2794
shalc	935	limo	2804
lime	1000	broken lime	2820
shale	1044	lime	2865
limo	1074	broken lime	2875
shale and sholls	1258	lime	2891
sdv shalo	1270	broken lime	2916
lime	1320	lime	3107
shale and sholls	1343	shale and lime	3138
lime	1356	lime	3155
shale and shells	1419	shale and sholls	3251
sand	1439	shale	3273
lime	1453	chat	3361
broken limo	1529		
shale	1582	Total Depth.	
broken limo	1605		
limo	1625		
shale	1648		
broken limo	1770		
shalo	1846		
broken lime	1908		
shalo	1974		
lime and shale	2112		
shalo and shells	2217		
sdv lime	2232		
broken limo	2273		
shale	2326		
broken lime	2343		
shale and shells	2395		
broken lime	2452		
shale	2475		
shale sand streaks	2514		
limo	2576		
broken lime	2587		
lime	2654		