

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.
412 Union National Bank Bldg., Wichita, Kansas.


Plotted
9.015
10-24-11 W

TRANSWESTERN OIL CO.
Mary Bankor "D" No. 2

SEC. 10 T. 24 R. 11W.
CWL SW SE

Total Depth. 3832'
Comm. 10-9-40 Comp. 10-27-40
Shot or Treated.
Contractor. Iron Drilling Co.
Issued 12-28-40

County Stafford.



CASING.

103/4" 247'
7" 3761'

Elevation.

Production. Pot. 3674 B.

Figures Indicate Bottom of Formations.

sand	105	shale and red bed	3373
red bed shale and shells	275	lime	3403
red bed and shale	537	lime and shale	3416
anhydrite	556	lime soft in spots with	
shale and shells	1082	strks of chert	3430
salt and shell	1414	lime with soft ore, porous	
lime and shale	1600	spots	3482
shale and shells	1604	lime	3490
anhydrite	1636	lime and chert	3516
lime broken	1714	shale sticky	3527
chert	1719	lime	3533
lime and chert	1740	lime and shale	3570
lime and shale	1765	lime with porous or soft	
shale	1772	spots	3595
cherty lime	1837	lime and shale	3620
lime and shale breaks	1955	lime and chert	3666
lime and shale	2019	lime & chert with some	
lime broken Sh. & red rock	2129	chert	3709
shale and shells	2197	shale with some chert	3740
lime broken	2209	shale and chert	3771
lime and shale	2257	shale and lime	3800
broken lime	2270	lime and shale	3815
shale	2285	lime and chert	3832
broken lime	2320	Total Depth.	
sharp lime	2359		
shale and lime	2480		
shale and shells	2522		
lime and shale	2574		
lime	2590		
shale	2619		
sticky shale	2630		
broken lime	2665		
broken lime, some chert	2722	lime	3110
lime	2728	lime and shale strks	3150
shale and shells	2822	lime with porous Ore soft	
broken lime	2845	spots	3165
shale	2870	lime	3177
sharp sdy lime	2900	lime broken	3221
lime	2919	shale and shells	3270
lime broken chert strks	2981	red bed	3284
lime	3008	lime and shale	3298
shale	3015	lime and shale some red shale	3356
lime and shale strks	3060		

Total Depth corrected to 3829' -
3' taken off for Rotary table.