

TORREY & FEASTER.
McConaughay No. 1

SEC. 8 T. 24 R. 13W.
NE SE NW

Total Depth, 4155
Comm. 10-25-37 Comp. 11-19-37
Shot or Treated.
Contractor.
Issued. 12-18-37

County Stafford.

DEC 18 1937



CASING.

13" 182'

Elevation.

Production. DRY.

Figures Indicate Bottom of Formations.

sand	182	broken limo no oil stain	3690
rod rock and shells	475	limo hard	3760 3708'
rod rock and shale	794	broken limo	3712
shale blue and shells	941	limo	3770
shale and shells	1224	limo and shale	3786
shale and shells & salt	1530	lime	3837
shale and salt	1654	limo and shale	3872
limo and shale	1748	limo and shale hard	3892
anhydrite	1760	limo and shale	3954
limo and shale	1879	conglomerate	3972
limo hard	1917	lime	3985
limo and shale	2135	conglomerate	3990
limo	2145	conglomerate and shale	4015
limo hard	2175	limo	4028
broken limo	2227	Viola limo	4033
broken limo and shale	2289	chat	4040
limo	2315	chert	4072
broken limo	2340	limo	4105
limo and shale	2513	shale	4130
limo	2566	limo	4155
lime and shale	2850		
lime	2860	Total Depth.	
shale and shells	2885		
limo and shale	3017		
limo	3121		
limo and shale	3139		
broken limo	3181		
limo and shale	3200		
limo hard	3223		
limo and shale	3300		
limo hard	3332		
limo	3340		
limo and shale	3370		
limo	3388		
limo and shale	3415		
slate hard blue	3430		
limo hard	3445		
broken limo	3458		
shale hard blue	3580		
K. C. limo	3635		
limo	3687		