

Superior Testers Enterprises, Inc.

R.R. 3, Box 295B, Great Bend, Kansas 67530

(316) 792-6902

Date 10-16-1999 Location 1/2-1/2-S/E 36-24-16 W Elevation 2061 K.B. County Edwards

Company F.G. Hall Company LLC Number of Copies 5

Charts Mailed to 6427 East Kellogg P.O. Box 780 167 Wichita Kansas 67278-0167

Drilling Contractor STERLING Drilling Rig #4

Length Drill Pipe 2463 I.D. Drill Pipe 3.80 Tool Joint Size 4 1/2" X.H.

Length Weight Pipe NONE I.D. Weight Pipe NONE Tool Joint Size NONE

Length Drill Collars 248 I.D. Drill Collars 2.25 Tool Joint Size 4 1/2" X.H.

Top Packer Depth 2727 Bottom Packer Depth 2732 Number of Packers 2 Packer Size 6 3/4"

TESTED FROM 2782 TO 2755 ANCHOR LENGTH 23 TOTAL DEPTH 2755 Hole Size 7 1/2"

LEASE & WELL NO. Enlow #5-36 FORMATION TESTED Red Eagle TEST NO. 4

Mud Weight 9.9 Viscosity 48 Water Loss 10.81 Chlorides - Pits 22000 D.S.T. _____

Maximum Temp. 92 °F Initial Hydrostatic Pressure (A) 1284 P.S.I. Final Hydrostatic Pressure (H) 1264 P.S.I.

Tool Open I.F.P. from 4:00 A.m to 4:15 A.m 15 min

Tool Closed I.C.I.P. from 4:15 A.m to 4:45 A.m 30 min

Tool Open F.F.P. from 4:45 A.m to 5:00 A.m 15 min

Tool Closed F.C.I.P. from 5:00 A.m to 5:30 A.m 30 min

Initial Blow WEAK blow for 6 minutes died flushed tool Good Surge - no help

Final Blow no blow - flushed tool - Good Surge - no help

Total Feet Recovered 75 Gravity of Oil _____ Correc _____

75 Feet of Thick heavy mud %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of MISRUN %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Feet of _____ %Gas _____ %Oil _____ %Mud _____ %Wa _____

Remarks SLID Tool 8-10 feet to bottom & PLUGGED Tool & Anchor

Extra Equipment - Jars NONE Safety Joint YES Extra Packer NONE Straddle NONE Hook Wall NONE

Top Recorder No. 78225 Clock No. Electronic Depth 2748 Cir. Sub NONE Sampler NONE

Bottom Recorder No. 13189 Clock No. 41441 Depth 2752 Insurance NONE

Price of Job _____

Tool Operator Sane Busby

Approved By _____

Superior Testers Enterprises, Inc. shall not be liable for damage of any kind to property or personnel of the one for whom a test is made, of for any loss suffered sustained, directly or indirectly, through the use of its equipment, or its statements opinion concerning the results of any test. Tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.

N 11013