




## BEE FORMATION TESTING CO., INC.

DATE 3-6-55

P. O. BOX 491

No 719

GREAT BEND, KANSAS

CUSTOMER'S  
ORDER NO.

NAME OF COMPANY ANSCUTZ Drilling Co.  
 ADDRESS TO MAIL INVOICE 709 Union Natl Bank Bldg Wichita  
 ADDRESS TO MAIL PRESSURE CHARTS SAME  
 LEASE HAILEY WELL NO. 1 COUNTY STAFFORD STATE KANS

TESTER F. H. ENSMINGER APPROVED George Reed  
 DRILL STEM TEST NO. 1 SUCCESSFUL NO. MIS-RUN NO. NO.  
 SIZE HOLE 7 7/8 TOOL JT. 4 1/2 F.H.  
 RUBBER SIZE 6 3/4 TEST TOOL SIZE 4 5/8  
 PACKER SET AT 3849 ANCHOR SIZE 4 1/2  
 TOTAL DEPTH WELL 3868 LENGTH ANCHOR 19  
 PRESSURE RECORDER CAP. 2500 + 3500 DRILL PIPE RUN: DRY ✓ WITH FLUID

## RESULTS:

PACKER SET 1108 P. M. TOOL OPEN 1110 P. M. TOOL OPEN \_\_\_\_\_ HRS.  
 BLOW Air through our test.

RECOVERY 62 ft slightly oil cur mud.

SHUT IN PRESSURE TIME \_\_\_\_\_ MUD WT. 10.1 VIS. 46 WATER LOSS 18.5 cc  
 BHP 450 IFP 0 FFP 0 HYDROSTATIC HEAD 2000  
 EXTRA EQUIPMENT NONE JARS \_\_\_\_\_ NO. \_\_\_\_\_ SIZE \_\_\_\_\_  
 OPERATOR TIME 8 TOOL RENTAL TIME 6

BEE FORMATION TESTING CO., INC.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.