

Lloyd L. Clarke
Phone TU 6-4159

John W. Clarke
Phone TU 6-5986



CLARKE CORPORATION • P.O. BOX 187 • MEDICINE LODGE, KS. 6704

Elmo Morgenstern
Phone TU 6-5858

Office Phone
TU 6-4214

WELL SERVICING RECORD

Area or Pool _____ Date of Report 8-19-68
Company Glenn Rupe
Work Started: Date 7-31-68 Work Completed: Date 8-19-68
Lease Name Taylor Well No. 1
Work Performed Worked Over

WELL RECORD

PULLED FROM WELL			EQUIPMENT	RERAN IN WELL		
Feet	Joints	Description		Feet	Joints	Description
			Mud Anchor	10	1	2"
			Perforations	3	1	2"
			Wkg. Barrel	1	1	Seating Nipple
			Hold Down			
			Tubing		150	2" EUE 8rd
			Tubing			
			Tubing Subs	6	1	2" X6'
			Pump			
			Rods			
			Rods			
			Rods			
			Rod Subs			
			Polished Rod			
			Stdg. Valve			
			Travg. Valve			
			Gas Anchor			

Tubing Leak _____
Location of tbg. catcher, pkr., anchor _____ Stroke _____ in. at _____ s. p. m.

RECORD OF ROD BREAKS

SIZE AND TYPE OF ROD	KIND OF BREAK	NO. OF RODS DEEP	DEEP	SIZE AND TYPE REPLACEMENT

Signed Don Haddock
(Unit Operator's Name)