

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.
412 Union National Bank Bldg, Wichita, Kansas.

DRILLERS GAS COMPANY.
Gerber No. 1.

SEC. 35 T. 27 R. 11W.
Cen $E\frac{1}{2}$ $E\frac{1}{2}$
660' W of NE $SE\frac{1}{4}$

Total Depth. 4142.
Comm. 8-19-39 Comp. 9-19-39
Shot or Treated.
Contractor. Springrose Drlg. Co.
Issued. 10-21-39

County Pratt.



CASING.

103 1/4" 388'
7" 4126'

Elevation.

Production. 28,888,000 G.

Figures Indicate Bottom of Formations.

surface	140	lime	2855
red rock	275	broken lime	2890
red rock and sand	350	lime	2900
red rock	600	shale	2920
shale and shells	1175	lime	2930
shale and salt	1385	sdv lime	2950
shale and lime	1395	lime	3120
sticky gyp	1430	broken lime	3130
lime and shale	1530	shale	3160
shale and gyp	1570	shale and lime	3195
broken lime	1620	broken lime	3255
shale and gyp	1640	lime hard	3280
broken lime	1660	lime	3290
shale and gyp	1670	sand and shale	3415
broken lime	1700	shale hard blk	3443
shale and lime	1770	shale blk	3490
lime shells and shale	1820	sdv lime	3505
lime and shale	1830	shale and lime	3645
sdv lime	1870	sdv lime	3685
lime	1880	lime and shale	3707
shale and lime	1920	sand and shale	3715
broken lime	1950	sdv lime	3725
shale blue	1970	lime	3875
broken lime	1985	lime broken	3927
lime	2020	ohat	3953
shale lime shells	2060	lime and shale	4030
broken lime	2080	shale	4105
lime	2110	shale and lime	4142
sticky shale	2120	Total Depth.	
sticky shale & lime	2125		
lime and shale	2132		
lime	2165		
broken lime	2205		
shale and lime	2230		
sdv lime	2260		
brown lime	2270		
shale and lime	2285		
shale and lime shells	2430		
lime and shale	2625		
lime	2635		
lime hard	2665		
lime broken	2675		
shale and lime	2685		
lime	2760		
broken lime	2810		