

3

27

15W

SECTION _____ TOWNSHIP _____ RANGE _____

#1 Stotts

WELL NO. _____

COMPANY Tennessee Gas Trans.

NORTH

C 3E NE

WEST

EAST

SOUTH

Pratt

SEC.

TWP.

KANSAS

3

27 S

15 W

WELL NO.

1 Stotts

FARM

COMPANY

Tennessee Gas Trans.

CONTRACTOR

Sterling Drlg.
Carver-Robbins.


____ FT. FROM N. LINE

____ FT. FROM S. LINE

____ FT. FROM E. LINE

____ FT. FROM W. LINE

NORTH



C SE NE

SOUTH

SDX-3/4 mile

ELEVATION

REPORT

1957

8/14

Location

(FR Tkt)

County Pratt Elev. _____
 Sec. 3 Twp. 27 Rge. 15W
 Company Tennessee Gas Trans.
 Farm Name Stotts No. 1

Co.

Lse.

No.

Sec.

T.

R.

TOPS	DEPTH	LOG	DATUM
Anh.			
TP.			
H.			
Tr.			
Dg.			
BL.			
L.			
K.C.			
B.K.C.			
Ce.			
C.			
M.			
M.			
K.			
Mz.			
Me.			
V.			
S.			
S.			
A.			
R.			
Pe.			
G.			
T.D.			

Loc. in Sec. _____

C SE NE

Geol. _____

Contr. _____

Sterling Drilling

Pool _____

Carver-Robbins

FIRST REPORT

AUG 14 57

SDX-

3/4 mile

Date Comm. _____

Location _____

JUL 14 1957

M.M.

26

County PrattElev. 2057Sec. 3Twp. 27Rge. 15WCompany Tennessee Gas Trans.

Stotts

No. 1

Co.

Lse.

No.

Sec.

T.

R.

	DEPTH	LOG	DATUM
Apk.			
TP.			
H. <u>ecc.</u>	<u>3758</u>		
Tr. <u>Toy</u>	<u>3778</u>		
Dg. <u>Dug</u>	<u>3788</u>		
Bl. <u>By 1/200</u>	<u>3910</u>		
L. <u>By 1/200</u>	<u>3934</u>		
K.C.			
B.K.C.			
Ce. <u>34</u>	<u>4376</u>		
C. <u>cut 1/2 m</u>	<u>4405</u>		
M.			
M.			
K.			
Mz.			
Ma.			
V.	<u>4464</u>		
S.	<u>4557</u>		
S.			
A.	<u>4639</u>		
R.			
PE.			
G.			
T.D.	<u>4663</u>		

Loc. in Sec. C SE NE

Geol.

Contr.

Sterling Dr.

Pool

Carver-Robbins

ABANDONED

3/4 mile

SEP 11 '57

Date Comm. 8-14

Tito

Location AW 4137 8@ 326/2505 + 2530AUG 28 '57 DST 4055-95 1hr run60' GCM + 210' SGCM BHP1505/20" ID 4130 SEP 4 '57 DST2123-58 1hr 60' w try MBH 1462 -1240/20" FP 28-30DST 4354-89 1hr 20/50"rec 40' M 1BH 1170 FBH 1150/20"DST 4378-99 35" rec

10' M NO press DST 4380-4450
1 hr rec 40' M SPK oil BHP
105 - FBH 0/20" No log

D + a (Hold)

SEP 11 52

3-27-15W

C se ne