

Sumner


KANSAS

DX 78-1

Section 33 Township 31 Range 1W

Well No. #136 Wellington Unit

Company CRA & SUNRAY



1956			
12/26	TD 3239'	Down for repairs	
12/27	Drlg. 3514'		
12/28	Coring @ 3656'		
12/31	Circulating @ 3664'		
1957			
1/2	TD 3695'	WOC - 5 $\frac{1}{2}$ " @ 3666'	
1/3	TD 3695'	WOC - 5 $\frac{1}{2}$ " csg.	
1/4	"	"	"
1/7	TD 3695'	WOC - 5 $\frac{1}{2}$ " csg.	
1/8	TD 3695'	CO to TD	
1/9	TD 3695'	Testing.	
1/10	TD 3695'	Swabbing load oil	
		Open hole 3666-3695'	
1/11	TD 3695'	Bailing & Testing.	
		Open hole 3666-3695'	
1/14	TD 3695'	Instl. Pumping Unit.	
1/15	"	"	"
1/16	"	"	"
1/17	"	"	"
1/18	"	"	"
1/21	"	"	"
1/22	TD 3695'	"	"
1/23	TD 3695'	"	"
1/24	"	"	"
1/25	"	"	"
1/28	"	"	"
1/29	"	"	"
1/30	"	"	"
1/31	TD 3695'	"	"
2/1	TD 3695'	"	"
2/4	"	"	"
2/5	"	"	"
2/6	TD 3695'	Waiting on Engine	
2/7	"	"	
2/8	"	"	
2/11	TD 3695'	Pumping on test.	
2/12	TD 3695'	Pumped 3 BO 24 hrs. Open	
		hole 3666-3695' Miss Zone.	
	Complete		(DR#30-1957)

[illegible]

Date Comm.

MIRT & RURT

20

229

SUNRAY

Elev. 1258

31

Rgs. 1W

C. A. A. & Sunray

Farm Name

Wellington Unit

No.

136

TOPS	DEPTH	LOG	DATUM	Loc. in Sec.
Anh.				NW NW NW
Tr.				
Dg.				
Bl.				
L.				
K.C.		3025		Geol.
B.K.C.				Contr.
Ce.				Veeder Tools
C.				
M. chert	3644	3645		Pool
M. "B" zn		3654		Wellington
K.				
Mz.				
Me.				
V.				
S.				
S.				
A.				
R.				
Pe.				
G.				
T.D. 3699	2950			

0	FEB 13 '57
COMPLETE	

Date Comm.

MLT & HURT DEC 5 '56 11-28-56

858 321/250 twist OFF

@ 2960 DEC 12 '56 Fshg. DEC 13 '56

Lost hole skid R19 10' North

858 314.93/240 D 2050

DEC 16 '56 DST 3163-77 1hr 30' VS BCM

BHP 855/30 DST 3186-3215 1hr

18" VS BCM BHP 805/30 D 3514

JAN 2 '57 5 1/2 3666/100

CO 3695 TB 5000 oil + 6
 GSW 30" 50 gal Acid
 Lost Part Load 13 & Ld.

JAN 10 '57 TB 2.88 BO + 8.24 BW
 10 24 hrs JAN 10 '57 JAN 10 '57 FEB 6 '57

FEB 13 '57 X P. 2.97 BO + 22.30
 BW 24 hrs.