


Section.....5.....Township.....32.....Range.....1-W.....

Well Number #7 Carr.....

Company.....Texas.....



Sec. 5 Twp. 32 R. 1-W


Well No. #7 Carr Farm
Texas Company

 Ft. from N. Line

330 Ft. from S. Line

 Ft. from E. Line

330 Ft. from W. Line



Date	REPORT
1937	
7/21	Location
7/30	R. R.
8/6	12" @ 347'. Woc.
8/13	" " "
8/20	Drlg. 1930'.
8/28	Drlg. 3135'.
9/3	Chat 3653'. T.D. 3656'.
	Rng. 8".
9/10	8" @ 3656'. SD repairs.
9/17	8" @ 3656'. C.O.
9/24	T.D. 3758'. Shot 40 qts.
	3000 acid. No test.
	Rec. 12½'. Misner 4965½'.
	Viola 4966'. Fshg. Smell oil.

OVER

1937

9/29

8" @ 3656'.

Chat 3653'.

T.D. 3758'.

Shot 40 qts.

3000 acid.

S.O. & 2 B.W. per hour.

COMPLETED

Summer

Map No. 31 Sec. 5 Twp. 32 R. 1 W

Well No. 7-Carr

Texas Company

Contractor

FIRST REPORT

SECTION PLAT

		0	

_____ Ft. from N. Line

330 Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Location ✓

Rig up _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUL 21 1937 19

H. D. Hatfield

Scout

Map No. 31 Sec. 5 Twp. 32 R. 1W

Well No. 7-Carr

Texas

Company _____

Contractor _____

ABANDONED

SW NE

SECTION PLAT

		0	

_____ Ft. from N. Line

330 Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Location _____

Rig up _____

Drilling and Remarks:

*shot 40 qts
3000 acid
S.O. & 2 BW
Per hr*

D & A

RECORD

Cased 8 in., 3656 ft.

Sand Chat 3653

Gas _____

Oil _____

Total Depth 3758

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

SEP 29 1937

19

H. D. Hatfield

Scout