

Trilobite Testing L.L.C.

Bottom hole pressure build-up test / Multi-point back pressure test

Company _____ Date _____

Address _____

Well Name & No. Cary 36-16

Legal Description Sec. 36 Twp. 32 Rge. 19 Co. Conrad State. _____

Field/pool _____ Elev. _____ Recorder # _____

Tubing _____ in. @ _____ ft.

Test type _____ Test Interval _____ Status _____

Date & Time Started _____ Date & Time Ended _____

Duration: _____ Sample Rate: _____

Duration: _____ Sample Rate: _____

Duration: _____ Sample Rate: _____

Duration: _____ Sample Rate: _____

Duration: _____ Sample Rate: _____

Duration: _____ Sample Rate: _____

Duration: _____ Sample Rate: _____

Mileage _____

628
536)

meter pressure

Remarks	Time	Orifice Size	CFR Pressure	Tubing Pressure	Casing Pressure	Temp	Flow
hooked up rec	10:50		DIFF		1435		
open lub-dr	11:37			1405			
3500'	13:38						stop
4000'	13:46						
4250	13:59						
4500	14:01						
4750	14:08				1443		
5000	14:16						
5100	14:23						
5200	14:31						
5124				1410	1445		
started super	14:45						
open rd well	15:15			1400	1430		
5164" →	15:45		5.5	↑	↑	93	
				1365	1400		
	15:55		18				
	16:00			1352 1345	1382		
1st pt	16:15	70	17	1318	1360	93	
	16:20	72	33	1275	1320	90	
	16:35	74	30	1257	1310	87	
	16:45	74	29	1250	1300	85	
	17:00	72	27	1215	1275	88	
2nd point	17:25	70	25	1190	1260	88	
	17:30	74	35	1144	1215	88	
	17:45	76	18	1140	1210	89	
	18:00	77	20	1126	1200	88	
3rd pt	18:15	78 78	17.5	1118	1195	88	
	18:45	78	16.5	1090	1175	88	
pinked back	19:00	78	16.5	1075	1168	88	
	19:15	77	13.5	1072	1165	88	
	19:30	75	9	1070	1170		

006
0
0