

COMPANY \_\_\_\_\_ FARM Congrove 'A'3 WELL NO. \_\_\_\_\_  
 SEC \_\_\_\_\_ TWP \_\_\_\_\_ RGE \_\_\_\_\_ LOC \_\_\_\_\_ COUNTY \_\_\_\_\_ STATE \_\_\_\_\_  
 CONTRACTOR \_\_\_\_\_ SIZE HOLE \_\_\_\_\_ DRILL PIPE \_\_\_\_\_

REMARKS:

Core #1 6181-62 624  
 2894  
 -33 27

DATE \_\_\_\_\_

DEPTH	TIME O'CLOCK	MIN	REMARKS
01			
02			
03			sd, fn, fn grn,
04			
05			sub ang, sptd
06			
07			stn + floor
08			
09			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			ls, fn, lt gy,
22			xlh dn,
23			
24			vert frac
25			
26			
27			
28			
29			lm, lt gy, fn xlh
30			hnd vly fn grn sd
6231			vly slt grave -
32			
33			
34			
35			
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			

DEPTH	TIME O'CLOCK	MIN	REMARKS
51			
52			
53			
54			
55			
56			
57			
58			
59			
60			
61			
62			
63			
64			
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
6181			lm, sd, fn, fn grn
82			
83			interbedded w/
84			
85			dk sh dull floor
86			
87			
88			
89			
90			sd, wh, md fn grn
91			
92			sub rnd, same stn
93			
94			+ floor
95			
96			
97			
98			lm, lt gy, fn grn
99			
6200			dn, vert. frac