

TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 039944 14844

SEP 27 2010

Well Name & No. Sansarius Unit A1 Test No. 1 Date 9/21/10
 Company John O Form Inc Elevation 2230 KB 2222 GL
 Address 370 W Wichita Ave Russell KS
 Co. Rep / Geo. Steve Murphy Rig Discoven #1
 Location: Sec. 27 Twp. 3S Rge. 20W Co. Phillips State KS

Interval Tested 3485-3510 Zone Tested LKC C
 Anchor Length 25 Drill Pipe Run 3456 Mud Wt. 5.8
 Top Packer Depth 3480 Drill Collars Run 31 Vis 60
 Bottom Packer Depth 3485 Wt. Pipe Run _____ WL _____
 Total Depth 3510 Chlorides _____ ppm System LCM _____
 Blow Description Weak blow - died in 12 min
ff - no blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>5</u>	<u>Mud</u>				
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 5 BHT _____ Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic <u>1659</u>	☒ Test <u>1125</u>	T-On Location <u>2100</u>
(B) First Initial Flow <u>14</u>	☒ Jars <u>250</u>	T-Started <u>2130</u>
(C) First Final Flow <u>19</u>	☒ Safety Joint <u>275</u>	T-Open <u>2251</u>
(D) Initial Shut-In <u>847</u>	☐ Circ Sub _____	T-Pulled <u>0051</u>
(E) Second Initial Flow <u>18</u>	☐ Hourly Standby _____	T-Out <u>0214</u>
(F) Second Final Flow <u>19</u>	☐ Mileage <u>124 RT 155</u>	Comments _____
(G) Final Shut-In <u>791</u>	☐ Sampler _____	
(H) Final Hydrostatic <u>1628</u>	☐ Straddle _____	

Initial Open 30
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 30


☒ Shale Packer 250
☐ Extra Packer _____
☐ Extra Recorder _____
☐ Day Standby _____
☐ Accessibility _____
 Sub Total 1855

☐ Ruined Shale Packer _____
☐ Ruined Packer _____
☐ Extra Copies _____
 Sub Total 0
 Total 1855
 MP/DST Disc't _____

Approved By _____

Our Representative Paul Singer

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 039945

4/10

BY:

Well Name & No. Jansons Unit #1 Test No. 2 Date 9/22
 Company John O'Farmer Elevation 2230 KB 2222 GL
 Address _____
 Co. Rep / Geo. Steve Murphy Rig Discoun #1
 Location: Sec. 27 Twp. 35 Rge. 20W Co. Phillips State Ks

Interval Tested 3512-3530 Zone Tested LIC D
 Anchor Length 18 Drill Pipe Run 3456 Mud Wt. 8.9
 Top Packer Depth 3507 Drill Collars Run 31 Vis 58
 Bottom Packer Depth 3512 Wt. Pipe Run _____ WL _____
 Total Depth 3530 Chlorides _____ ppm System LCM _____
 Blow Description If walk surface blow

ff - no blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>5</u>	<u>Mud w/oil specks in mud</u>				
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total _____ BHT 72 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic <u>1708</u>	☒ Test <u>1125</u>	T-On Location <u>0800</u>
(B) First Initial Flow <u>15</u>	☒ Jars <u>L 250</u>	T-Started <u>0816</u>
(C) First Final Flow <u>20</u>	☒ Safety Joint <u>L 75</u>	T-Open <u>10:32</u>
(D) Initial Shut-In <u>1189</u>	☐ Circ Sub _____	T-Pulled <u>12:32</u>
(E) Second Initial Flow <u>22</u>	☐ Hourly Standby _____	T-Out _____
(F) Second Final Flow <u>25</u>	☐ Mileage <u>124 RT 155</u>	Comments _____
(G) Final Shut-In <u>1178</u>	☐ Sampler _____	
(H) Final Hydrostatic <u>1610</u>	☐ Straddle _____	

Initial Open 30
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 30


☒ Shale Packer L 200
☐ Extra Packer _____
☐ Extra Recorder _____
☐ Day Standby _____
☐ Accessibility _____
 Sub Total 1855

☐ Ruined Shale Packer _____
☐ Ruined Packer _____
☐ Extra Copies _____
 Sub Total 8
 Total 1855

Approved By _____

Our Representative Paul Simon

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 039946

RECEIVED
SEP 23 2010

Well Name & No. Jansons Unit #1 Test No. 03 Date 9/22/10
 Company John O. Farmer Elevation 2230 KB 2222 GL
 Address _____
 Co. Rep / Geo. Steve Murphy Rig Discovers 1
 Location: Sec. 22 Twp. 3s Rge. 20w Co. Phillips State Kr

Interval Tested 3536-3550 Zone Tested Licc F
 Anchor Length 14 Drill Pipe Run 3489 Mud Wt. 5.9
 Top Packer Depth 3531 Drill Collars Run 31 Vis 56
 Bottom Packer Depth 3536 Wt. Pipe Run _____ WL 8.0
 Total Depth 3550 Chlorides _____ ppm System LCM _____
 Blow Description weak surface blow - died in 5 minutes

ff - no blow
tool slot 3' before opening

Rec <u>2</u>	Feet of <u>50cm</u>	%gas <u>3</u>	%oil	%water <u>9</u>	%mud
Rec	Feet of <u>(free oil in tool)</u>	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 2 BHT 92 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic 1693
 (B) First Initial Flow 14
 (C) First Final Flow 16
 (D) Initial Shut-In 941
 (E) Second Initial Flow 17
 (F) Second Final Flow 17
 (G) Final Shut-In 693
 (H) Final Hydrostatic 1612

☐ Test 1125
☐ Jars X 250
☐ Safety Joint X 75
☐ Circ Sub _____
☐ Hourly Standby _____
☐ Mileage 124 RT 155
☐ Sampler _____
☐ Straddle _____
☐ Shale Packer X 250
☐ Extra Packer _____
☐ Extra Recorder _____
☐ Day Standby _____
☐ Accessibility _____
 Sub Total 1855

T-On Location 1800
 T-Started 1515
 T-Open 1757
 T-Pulled 2158
 T-Out 2338

Comments _____

Initial Open 30
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 30

☐ Ruined Shale Packer _____
☐ Ruined Packer _____
☐ Extra Copies _____
 Sub Total _____
 Total _____
 MP/DST Disc't _____

Approved By _____

Our Representative Paul Simpson

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 039941

SEP 27 2010

Well Name & No. JANSONIUS Unit #1 Test No. 4 Date 9-23-10
 Company John O. Former Inc Elevation 2230 KB 2228 GL
 Address _____
 Co. Rep / Geo. Steve Murphy Rig Discovery #1
 Location: Sec. 27 Twp. 3 Rge. 20 Co. Phillips State K5

Interval Tested 3610 — 3670 Zone Tested F-I-K-L LKC
 Anchor Length 60 Drill Pipe Run 3580 Mud Wt. 9.1
 Top Packer Depth 3605 Drill Collars Run 31 Vis 60
 Bottom Packer Depth 3610 Wt. Pipe Run — WL 8.8
 Total Depth 3670 Chlorides 1200 ppm System LCM 3/1#
 Blow Description F.F. Weal - died in 7 min.

F.F. No blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>3</u>	<u>60</u>				
<u>10</u>	<u>Mod</u>				

Rec Total 13 BHT 94 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic 1761
 (B) First Initial Flow 18
 (C) First Final Flow 25
 (D) Initial Shut-In 703
 (E) Second Initial Flow 27
 (F) Second Final Flow 30
 (G) Final Shut-In 213
 (H) Final Hydrostatic 1725

☐ Test 1125
☒ Jars X 250
☒ Safety Joint X 75
☐ Circ Sub _____
☐ Hourly Standby _____
☒ Mileage 124 RT 155
☐ Sampler _____
☐ Straddle _____
☒ Shale Packer X 250
☐ Extra Packer _____
☐ Extra Recorder _____
☐ Day Standby _____
☐ Accessibility _____
 Sub Total 1855

T-On Location 12:15
 T-Started 13:30
 T-Open 15:00
 T-Pulled 17:00
 T-Out 18:28
 Comments _____
☐ Ruined Shale Packer _____
☐ Ruined Packer _____
☐ Extra Copies _____
 Sub Total 0
 Total 1855
 MP/DST Disc't _____

Initial Open 30
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 30

Approved By _____

Our Representative

Dan Bangle

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.