Distributed By-
KANSAS GEOLOGICAL SOCIETY
508 East Murdock
WICHITA, KANSAS 67214

18-7-19W

KANSAS GEOLOGICAL SOCIETY
508 East Murdock
Wichita, Kansas
FEB 1 1980

Broken Arrow Drilling Company

ROOM 409 PETROLEUM BUILDING • TULSA, OKLAHOMA 74103 • AC 918-582-1181

DRILLER'S LOG

COMPANY: National Associated Petroleum Co.
Petroleum Building
Tulsa, Oklahoma 74103

FARM: Rose Culp NO. 1

TOTAL DEPTH 3475'

COMM.: 12-8-69 COMP.: 12-16-69

CONTRACTOR: BROKEN ARROW Drilling
Petroleum Building
Tulsa, Oklahoma 74103

SEC. 18 TWP. 7S RGE. 19W

LOCATION: SW-SE-SW

COUNTY: Rooks

ELEVATION 2008'

PRODUCTION: Oil Well

CASING RECORD: 203' New 8 5/8"

CEMENT RECORD: 110 sacks cement
100# AC, 200# CC

0'-45'	Soil
45'-1530'	Sand & Shale
1530'-1545'	Shale
1545-1583'	Anhydrite
1583'-1935'	Shale
1935'-2755'	Lime
2755'-3055'	Lime & Shale
3055'-3475	Lime
T. D. 3475'	

We herely certify that the above is a true copy of the Driller's Log for the above described well.

BROKEN ARROW DRILLING COMPANY
By:

Jack Roberts