

SEE TESTING COMPANY INC.

SUB-SURFACE RECORD

COMPANY Anderson-Prichard Oil Corp. DATE OF TEST November 6, 1953
 WELL NO. 3 TEST NO. 1 LEASE Sanford
 PRESSURE RECORDER CAP 2500# MUD WT. 10.1
 TOTAL DEPTH 3555' PACKER SET AT 3525'
 RECOVERY 580' drilling mud

TOOL OPEN: 1 hour
 CHOKE SIZE: TOP $\frac{1}{2}$ " BOTTOM $\frac{1}{2}$ " NO. OF COPIES 1
 OPERATOR J.R. Thomas TEST TICKET NO. 151
 SHUT IN PRESSURE TIME 15 minutes BHP 1000# IFP 200# FFP 300# MUD COLUMN PRESSURE 1870#
 PACKER SEAT FAILURE TOOL PLUGGED ANCHOR PLUGGED




LEE TESTING COMPANY INC.

SUB-SURFACE RECORD

COMPANY Anderson-Prichard Oil Corp. DATE OF TEST November 7, 1953
WELL NO. 3 TEST NO. 2 LEASE Sanford
PRESSURE RECORDER CAP 3500# MUD WT. 10.2
TOTAL DEPTH 3580' PACKER SET AT 3562'
RECOVERY 120' drilling mud; 60' oil cut mud; 120' heavily oil cut mud

TOOL OPEN: 1 hour
CHOKE SIZE: TOP $\frac{1}{2}$ " BOTTOM $\frac{1}{2}$ " NO. OF COPIES 1
OPERATOR J.R. Thomas TEST TICKET NO. 189152
SHUT IN PRESSURE TIME 15 minutes BHP 200# IFP 0 FFP 0 MUD COLUMN PRESSURE 1891#
PACKER SEAT FAILURE TOOL PLUGGED ANCHOR PLUGGED



BEE TESTING COMPANY INC.

SUB-SURFACE RECORD

COMPANY Anderson-Pritchard Oil Corp. DATE OF TEST November 7, 1953
WELL NO. 3 TEST NO. 3 LEASE Sanford
PRESSURE RECORDER CAP 2500# & 3500# MUD WT. 10.2
TOTAL DEPTH 3600' PACKER SET AT 3586'
RECOVERY Packer Failure

TOOL OPEN: _____
CHOKE SIZE: TOP _____ BOTTOM _____ NO. OF COPIES _____
OPERATOR _____ TEST TICKET NO. L# 153
SHUT IN PRESSURE TIME _____ BHP _____ IFP _____ FFP _____ MUD COLUMN PRESSURE _____
PACKER SEAT FAILURE X TOOL PLUGGED _____ ANCHOR PLUGGED _____



BEE TESTING COMPANY INC.

SUB-SURFACE RECORD

COMPANY Anderson & Prichard Oil Corp. DATE OF TEST November 8, 1953

WELL NO. 3 TEST NO. 4 LEASE Sanford

PRESSURE RECORDER CAP 2500# & 3500# MUD WT. 10.2

TOTAL DEPTH 3600' PACKER SET AT 3583'

RECOVERY _____

TOOL OPEN: _____

CHOKE SIZE: TOP _____ BOTTOM _____ NO. OF COPIES 1

OPERATOR _____ TEST TICKET NO. 154

SHUT IN PRESSURE TIME _____ BHP _____ IFP _____ FFP _____ MUD COLUMN PRESSURE _____

PACKER SEAT FAILURE X TOOL PLUGGED _____ ANCHOR PLUGGED _____

