

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY
412 Union National Bank Bldg, Wichita, Kansas.

58660 ✓

W.L. HARTMAN & THREE WAY DRLG. CO.
Andreson No. 1

SEC. 28 T. 9 R. 16 W.
CSL SW SW.

15-163-00065
County Rocks.

Total Depth. 3426
Comm. 9-4-42 Comp. 10-17-42
Shot or Treated.
Contractor. Three Way Drilling Co.
Issued. 11-7-42

CASING.

10" 125' Cem.
7" 3097'
5½" 3345'

Elevation.

Production. DRY.

Figures Indicate Bottom of Formations.

shale blue	265	lime and shells	3224
shale and shells	575	lime	3232
shale	650	shale	3237
sdv shale	695	lime broken	3242
sand	798	lime broken & shale	3252
sdv shale and iron	965	lime	3269
shale	1180	broken lime	3274
shale and shells	1264	lime	3286
anhydrite	1303	1500 gal acid.	
shale and shells	1600	testing oil from	3282-86 ✓
shale and lime	1630	Swabbing and cleaning	
salt and shells	1722	out. Hole filled up 70' with	
salt and shale	1745	cuttings. After acidizing.	
shale and shells	1784	shale	3285- 96
lime	1825	lime	3303
broken lime	1865	broken lime	3308
shale and shells	1885	lime	3314
lime and shale	1982	lime hard	3318
broken lime	1995	lime soft	3321 HFW
lime	2000	lime	3343
broken lime	2055	shale	3345
shale and lime	2110	lime	3372
sdv lime	2135	shale	3376
lime	2144	lime	3422
lime broken	2220	sdv lime	3426
lime	2276	Total Depth.	
lime and red rock	2310		
lime	2360		
lime broken	2447		
shale	2467		
shale and shells	2495		
lime and shale	2565		
shale	2591		
lime	2604		
shale	2624		
shale and shells	2778		
shale	2816		
lime	2854		
lime and shale	2934		
shale and shells	2952		
lime	2970		
shale	2976		
lime	3051		
shale	3063		
lime cherty	3072		
lime	3198.8		
Standardized			
lime	3211		
shale broken	3214		
shale red & green	3218		