

24-9-20W

15-103-20384

AUG 14 1971

COMPANY I. O. MILLER

FARM Miller

NO. 1

SEC. 24 T. 9 R. 20W
LOC. NW NE SE

TOTAL DEPTH 3629

COMM. 7-27-71

COMP. 8-3-71


SHOT OR TREATED

CONTRACTOR Red Tiger Drlg.

ISSUED

COUNTY Rocks

KANSAS



CASING

20	10
15	8 5/8" @ 211' W/150 Sx
12	6
13	5

ELEVATION 2128'RB

PRODUCTION Dry/Arb

FIGURES INDICATE BOTTOM OF FORMATIONS

Topeka	3131
Limestone, Staining, no value	3264
Lansing	3350
Limestone, no free oil no odor	3366
Cherty limestone, light staining	3438
Limestone, staining, no free oil	3503
Arbuckle	3602
Cherty Dolomite, faint odor	3607
Cherty Dolomite	3613
Dolomite, black stringy oil	3616
Dolomite, no free oil or odor	3629
Total Depth	

DRILL STEM TESTS:

DST # 1	Tool open 27 minutes. Very weak blow for 4 minutes.
3603-3609	Recovered 2' drilling mud.
Arbuckle	BHP 42# in 25 minutes
	IFP 21# in 25 minutes
	FFP 27# in 25 minutes

SAMPLE TOPS:

Anhydrite	1568
Howard	3104
Topeka	3131
Heebner	3309
Toronto	3334
Lansing	3350
Arbuckle	3602