4-041812 15-147-00472-00-00

TO:	API Number: 15 11-28-50
STATE CORPORATION COMMISSION 10-24	
CONSERVATION DIVISION - PLUGGING / C	<u>NE AW 5W</u>
130 SOUTH MARKET, SUITE 2078	2310 feet from N section line
WICHITA, KANSAS 67202	990 feet from W section line
Operator license# 5242	Lease: Huffstutter Well #_C-2
Operator receipes	
Operator: Petroleum Management, Inc.	County: Phillips 1/5.31
Address: 14201 East Central	Well total depth 3548 feet
Wichita, Kansas 67230	Conductor Pipe: 0 inch @ 0 feet Surface pipe 8 5/8 Inch @ 188 feet
	w/125sx.cmt.
	,, ,
Aband. oil well_x_, Gas well, Input well_	, SWD, D & A
	
Plugging contractor: Allied Cementing	License#
	* ·
Address: Russell, Kansas 67665	100 March 100 Ma
Company to plug at: Hour: 9:00 A.M. Day: 24 Mor.	nth: October Year 1996
company to plug at. noar.	
Plugging proposal received from: Gary Reed	
Company: Petroleum Management, Inc.	Phone:
	with 1/4# F.C 500# hulls.
Were: Order 250 sxs 60/40 pozmix with 10% gel 5 1/2" casing set at 3548' w/150 sxs cement.	
Dakota at 1010' - W.L.M. at 3450'.	
	# .
Plugging Proposal Received by: Dennis L. Hamel	e se
Plugging operations attended by agent? All[}	
Completed: Hour: 3:30 P.M., Day: 24, Month:	. October , Year: 1996
a to all all and a constant to the constant to	/OH G D
Actual plugging report: R.U. Cementers to 8 5 Max. P.S.I. 300#. R.U. Cementers to 5 1/2" ca	
followed with 14 sxs gel, followed with 175 sx	

Remarks: Allied Cementing.	
Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD	Anhy.plug: YES X NO
Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES X , CALC , NO	Dakota plug: YESX_, NO
Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES X , CALC , NO Plugged chapagh TUBING , CASING X	Dakota plug: YESX_, NO
Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES X , CALC , NO Plugged chrough TUBING , CASING X	Dakota plug: YES X , NO GL
Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES X , CALC , NO Plugged chrough TUBING , CASING X	Dakota plug: YES X, NO GL GL GL GL
Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES X , CALC , NO Plugged chrough TUBING , CASING X	Dakota plug: YES X , NO GL